



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MITSUBISHI LANCER EX

GLX | 91,536 KM

Car highlights



Great Parking Assistance

Reverse Camera



Bluetooth

Enjoy your drive with bluetooth



Music System
















Enjoy your drive with music system



Amazing Comfort


Power driver seat

Basic Details

 Kilometers	91536	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JMYSTCY4AGU737575		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience		
Rear Armrest with cupholder		Central Armrest 
 Exteriors		
Rear Bumper Spoiler		
 Safety & Security		

Reverse Camera



Entertainment

Bluetooth Player



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Weather Strip: Colour faded		Handle: Light Scuffing < 50mm	
Rear left door		Rear right door	
Weather Strip: Colour faded		Handle: Scratch < 50mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Chip< 8mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm	

Trunk Condition

Trunk	
-------	---





Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	

Right A to B Pillar Colour Mismatch	⚠	Left B Pillar Condition: Scratch < 50mm, Colour mismatch/Low Brightness	⚠
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board Condition: Light Scuffing < 80mm	⚠
Windshield Condition			
Front Windshield Condition: Driver Side/Stone Chip Mark<5mm	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Condition: Light Scuffing < 80mm	⚠
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Paint Faded	⚠	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm, Paint Defects	⚠	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	⚠	Monogram	✓

Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	⚠
Transmission Fluid	✓	Rear Axle: Minor Damage	

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
------	--	--	--

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger Side Strip Not Working	!
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Gear Shift Knob: Scratch	!
Cup Holder	✓	Glove Box Glove Box: Glove Box Retainer Faulty	!

Steering Wheel	✓	Sunvisor Left: Sunvisor LHSMinor Smudge, Sunvisor RHS Minor Smudge	!
Seat Upholstery Passenger Seat: Minor Smudge/Cracks, Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Right Door: Scratch	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE