



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2019 HYUNDAI TUCSON

GL | 100,084 KM

VIN: TMAJ2813XKJ830878

### Car highlights



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Parking Sensors Rear



#### **Music System**
















Enjoy your drive with music system



#### **Amazing Comfort**




Power driver seat

Basic Details

 Kilometers	100084	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	TMAJ2813XKJ830878		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		✓	Steering Mounted Audio Controls
			✓
 <b>Exteriors</b>			
Fog Light Front		✓	
 <b>Safety &amp; Security</b>			

Parking Sensors Rear



Entertainment

USB Charging Port



Infotainment System



# 150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition


#### Front left door

Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm 

#### Front right door

Frame: Light Scuffing < 50mm 

#### Rear left door


Panel: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm 

#### Rear right door


Frame: Light Scuffing < 50mm 

### Fenders Condition

#### Left Fender

Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm 

#### Right Fender


Condition: Light Scuffing < 50mm, Scuffing > 50mm 

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Light Scuffing<50mm 


#### Right Quarter Panel

Condition: Chip<5mm, Low Visual Dent < 30mm 

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Light Scuffing < 80mm 

### Hood Condition

#### Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Paint Damage/ Low Brightness 

### Trunk Condition

Trunk 


### Trunk conditon


Trunk 

### Roof Condition


Roof 


#### Pillars Condition

Left A Pillar  
Inner Condition: Fair Use Wear 

Right A Pillar  
Condition: Colour Mismatch 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar  
Light Scuffing < 50mm 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 

Right B to C Pillar  
Low Visual Dent < 50mm 

Right B to C Pillar Beading 

Left C Pillar 


#### Running Board Condition

Left Running Board  
Condition: Light Scuffing < 80mm 

Right Running Board  
Front Right Sill Trim: Light Scuffing < 80mm 

#### Windshield Condition

Front Windshield  
Condition: Air Bubbles 

Rear Windshield  
Tint Fair Use Wear < 30mm 

#### Structural Assessment


Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top  
Beading: Crack/Fair Use Wear<50mm 

Head Light Support Condition 

Cowl Top

Cowl Top 

#### Rear View Mirror Condition

Left Hand Side Mirror 

Left Side Mirror 


Right Side Mirror  
Body: Light Scuffing < 50mm 

Right Hand Side Mirror 

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim 

Left Rear Alloy/ Rim 

Right Front Alloy/ Rim  
Rim: Alloy Edge Scuffing < 80mm 

Right Rear Alloy/ Rim 


Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Acid Marks/ Bird Dropping < 5mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap Scratch	!	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  <b>Electricals, Controls &amp; Lights</b> </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch Scratch	!
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts

Rear Center Seat Belt: Scratch



Head Rest



Door Controls And Trim

Front Left Door: Minor Scratch



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE