



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 TOYOTA COROLLA SE | 46,343 KM

VIN: RKLBB9HE0G5158524

Car highlights



Low Mileage

This car has been driven less than 15,000 km a year



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat


Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality




Left A Pillar Inner Condition: Fair Use Wear	(!)	Right A Pillar	•
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Chip < 8mm	(!)
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition Left Running Board Condition: Scratch < 80mm	(!)	Right Running Board	•
Windshield Condition Front Windshield	•	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Condition: Light Scuffing < 80mm	(!)
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	•	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓



Electricals, Controls & Lights

Keys



RHS Minor Smudge

Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks	!	Manual Seat Movement	•
Seat Belts Driver Seat: Fair Use Wear	!	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	!	Grab Handle	✓
Carpet Trunk Floor Carpet: Wear & Tear < 80mm	!	Headliner	✓
Rear View Mirror		Toolkit	
Real View WillTol		TOOME	
Tyres		Tooliut	
Tyres		Tooliut	
Tyres Condition	•	Left Hand Side Rear Tyre	•
Tyres Tyres Condition Left Hand Side Front Tyre	**		***
	***	Left Hand Side Rear Tyre	
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre	***	Left Hand Side Rear Tyre	
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	<65%	Left Hand Side Rear Tyre	<75%
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre Tyres Depth (Remaining)	<65% <75%	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	<75% <75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE