



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 MITSUBISHI MONTERO SPORT**

**GLX | 106,056 KM**

VIN: MMEMC21X1GH000503

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 106056            |  Specs             | Yes                  |
|  Engine           | 3.0L              |  Option Type       | Mid Option           |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MMEMC21X1GH000503 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   |  | Cruise Control                  |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors  |  | Central Armrest                 |  |
|  <b>Exteriors</b>                 |   |                                 |   |
| Fog Light Front  |  | Running Lights                  |  |

|  |   |                       |
|--|---|-----------------------|
| Halogen Headlights   | ✓ |                       |
|  <b>Safety &amp; Security</b> |   |                       |
| Parking Sensors Rear   | ✓ | Reverse Camera ✓      |
| Traction Control   | ✓ | Airbag Driver Front ✓ |
| ABS  | ✓ | Central Locking ✓     |
| Child Safety Locking   | ✓ |                       |
|  <b>Entertainment</b>         |   |                       |
| Bluetooth Player   | ✓ | USB player ✓          |

# 150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition


#### Front left door

Frame Extension Cover: Light Scuffing < 50mm 


#### Front right door

Panel: Light Scuffing < 50mm 

#### Rear left door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm 

#### Rear right door


Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm 

### Fenders Condition

#### Left Fender


Condition: Light Scuffing < 50 mm 

#### Right Fender


Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm 

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Low Visual Dent<30mm, Light Scuffing<50mm, Chip<5mm 

#### Right Quarter Panel


Condition: Light Scuffing<50mm, Low Visual Dent < 30mm 

### Front Bumper Condition

Front Bumper 


### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 

### Hood Condition

#### Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm 

### Trunk Condition

Trunk 

### Trunk conditon

Trunk 

## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar  
Chip < 8mm



Right B to C Pillar Beading



Left C Pillar  
Light Scuffing < 50mm



## Running Board Condition

Left Running Board



Condition: Light Scuffing < 80mm

Right Running Board



Condition: Light Scuffing < 80mm

## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Rim: Alloy Edge Scuffing < 80mm

Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



|                                    |   |  |   |
|------------------------------------|---|--|---|
| Wheel Arch                         | ✓ | Wheel cover                              | ✓ |
| Antenna                            | ✓ | Grill Condition<br>Light Scuffing < 50mm | ! |
| Monogram                           | ✓ | Window Glass                             | ✓ |
| Wiper                              | ✓ |  |   |
| Panel Condition                    |   |  |   |
| Rear Trunk Panel<br>Scratch < 50mm | ! |  |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Cap                       | ✓ | Fuel Tank          | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |

|  |   |                           |
|--|---|---------------------------|
| Suspension   |   |                           |
| Shock Absorbers  | ✓ |                           |
| <hr/>  |   |                           |
| <div> <div></div> <div>Electricals, Controls &amp; Lights</div> </div> |   |                           |
| Keys   |   |                           |
| Master Key   | ✓ | Spare Key(s) ✓            |
| Door Locks   |   |                           |
| Child Safety Locking   | ✓ |                           |
| Dashboard  |   |                           |
| Instrument Panel   | ✓ |                           |
| Airbags  |   |                           |
| Airbags  | ✓ |                           |
| Controls   | ✓ | Cruise Control ✓          |
| Infotainment Display   | ✓ | Engine Sensors ✓          |
| OBD Connector  | ✓ | Music System ✓            |
| Camera   | ✓ |                           |
| Lights   |   |                           |
| Headlight  |   |                           |
| Left: Light Scuff Marks < 50mm   | ! | Interior Lights ✓         |
| Tail Light Cluster   | ✓ | Daylight Running Lights ✓ |
| License Plate Light  | ✓ | Fog Lights ✓              |
| Air Conditioning   |   |                           |
| AC Cooling   | ✓ | AC Switch ✓               |
| AC System Leaks  | ✓ | Center AC Vent ✓          |
| Front Right AC Vent  | ✓ | Heater ✓                  |
| Rear Blower Switch   | ✓ | Rear Left AC Vent ✓       |
| Rear Defogger  |   |                           |
| Extensive Wear Of Strip  | ! | USB Charging Port ✓       |

Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor

Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage



Seat Upholstery

Driver Seat: Minor Fair Wear/Fade off



Manual Seat Movement



Seat Belts



Head Rest

Driver Seat: Fair Use Wear



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet



Headliner

Rear Left: Smudge/Disfiguration



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<65%

Spare Tyre

<45%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE