



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2016 LAND ROVER DISCOVERY SPORT

SI 4 | 98,874 KM

VIN: SALCA2BG9GH544694

### Car highlights



#### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Central Arm Rest**




Central arm rest for extra comfort








Basic Details

 Kilometers	98874	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	10 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	SALCA2BG9GH544694		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		✓	Power Tailgate/ Power Trunk
Central Armrest		✓	Remote Engine Start
 <b>Exteriors</b>			
Fog Light Front		✓	
 <b>Safety &amp; Security</b>			

Parking Sensors Rear		ABS	
Central Locking			
<div> <b>Entertainment</b></div>			
Bluetooth Player		USB Charging Port	
Infotainment System			





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Condition: Scratched, Cracked		Condition: Scratched, Cracked	
Rear left door		Rear right door	
Condition: Scratched, Dented, Cracked		Condition: Scratched, Cracked	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Scratched	

### Front Bumper Condition

Front Bumper	
Condition: Scratched	

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Reflector Broken, Scratched	








### Hood Condition

Hood	
Bonnet: Faded, Scratched	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Condition: Scratched		Condition: Scratched	
Left B Pillar		RHS Pillar B Condition	
Condition: Scratched			
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

## Running Board Condition

Left Running Board



Right Running Board



## Windshield Condition

Front Windshield

Condition: Beading Missing/Broken



Rear Windshield



## Structural Assessment

Chassis Condition



Apron



Boot Floor

Condition: Scratched



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Condition



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror

Body: Scratched



Left Side Mirror



Right Side Mirror

Body: Scratched



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim

Alloy Wheel: Nut Cover Missing



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratched



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

## **Steering, Suspension & Brakes**

Steering			
Steering wheel Condition: Trim Scratched	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

## **Electricals, Controls & Lights**

Keys			
Master Key Faded	!		
Remote Key Operations			
Keyless/ Remote Start	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Music System Steering Mounted Audio Controls: Scratched	!	Bluetooth Operations	✓

Lights			
Lights	✓	Headlight	✓
Interior Lights	✓	Tail Light Cluster	!
		Right Tail Lamp: Cracked	
Turn Signal Lights	✓	License Plate Light	✓
Back Up Light	✓	Fog Lights	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	!	Central Console	!
Dashboard And Instrument Panel: Scratched		Condition: Scratched	
Cup Holder	✓	Sunvisors	!
		Broken/Missing	
Seat Upholstery			
Driver Seat: Depressed/Pressure Mark, Faded	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	!
		Rear Right Door: Scratched	



Door Hinge Condition	✓	Carpet	!
		Front floor carpet: Stained	
Headliner	!	Rear View Mirror	✓
Headliner condition: Torn/Dirty			
Toolkit	✓		

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE