



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 FORD FOCUS**

**AMBIENTE | 123,450 KM**

VIN: WF0BC2KF5FLG70602

## **Car highlights**



### **Great Parking Assistance**

Reverse Camera



### **Bluetooth**

Enjoy your drive with bluetooth



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**











Power driver seat

Basic Details

 Kilometers	123450	 Specs	Yes
 Engine	1.6L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WF0BC2KF5FLG70602		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>				
Rear Bumper Spoiler		<div></div>	Halogen Headlights	<div></div>
<div> Safety &amp; Security</div>				
Reverse Camera		<div></div>	Traction Control	<div></div>
Airbag Driver Front		<div></div>	ABS	<div></div>
Central Locking		<div></div>	Child Safety Locking	<div></div>



Comfort & Convenience

Steering Mounted Audio  
Controls



Entertainment

Bluetooth Player



USB player



# 150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm, Low Visibility	
		Dent < 30mm	

Rear left door		Rear right door	
Panel: Low Visual Dent < 30mm, Light		Panel: Light Scuffing < 50mm, Low Visual	
Scuffing < 50mm, Paint Chip-off < 5mm		Dent < 30mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Low Visual Dent < 30mm, Light		Condition: Low Visual Dent < 30mm, Light	
Scuffing < 50 mm		Scuffing < 50mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Light Scuffing<50mm		Condition: Low Visual Dent < 30mm, Light	
		Scuffing<50mm	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Paint Chip-off	
< 5mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof 

#### Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar 

#### Running Board Condition

Left Running Board


Front Left Sill Trim: Minor Scuffing < 80mm,  
Low Visual Dent < 50mm 

Right Running Board

Front Right Sill Trim: Light Scuffing < 80mm 

#### Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear <  
50mm 

Rear Windshield 

#### Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

#### Rear View Mirror Condition

Left Hand Side Mirror 

Left Side Mirror 

Right Side Mirror 

Right Hand Side Mirror 

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face Light Scuffing < 50mm 

Left Rear Alloy/ Rim

Rim: Alloy Edge Scuffing > 50mm, Alloy Face  
Light Scuffing < 50mm 

Right Front Alloy/ Rim

Rim: Alloy Face Light Scuffing < 50mm 

Right Rear Alloy/ Rim

Rim: Alloy Face/Light Scuffing<50mm 


Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Broken/ Fair Use Wear	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Dent < 30mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  <b>Electricals, Controls &amp; Lights</b> </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	!	Interior Lights	✓
Left: Light Scuff Marks < 50mm			
Tail Light Cluster	!	Turn Signal Lights	!
Left Tail Lamp: Crack / Fair Use Wear < 5mm		Left ORVM: Light Scuffing < 50mm	
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent Crack/Fair Use Wear	!
Front Right AC Vent	!	Heater	✓
Fair Use Wear			
Rear Defogger	!	USB Charging Port	✓
Extensive Wear Of Strip			

Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Trim: Light Scuffing/Disfiguration



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor

Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE