



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 HYUNDAI Creta

S / GL | 119,013 KM

## Car highlights



### Great Parking Assistance

Reverse Camera, Parking Sensors Rear



### Music System

Enjoy your drive with music system



### Amazing Comfort

Power driver seat



### Tilt Steering wheel

Tilt steering wheel for extra comfort

## Basic Details

 Kilometers	<b>119013</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MALC281C3JM251066</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>	
Fog Light Front	
 <b>Safety &amp; Security</b>	
Parking Sensors Rear	
Reverse Camera	
Traction Control	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door

Panel: Dent < 30mm, Scratch < 50mm, Paint  
Chip-off < 5mm



Rear right door

Panel: Low Visual Dent < 30mm, Light  
Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Dent < 30mm, Scratch < 50mm,  
Paint Chip-off < 5mm



Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm,  
Paint Chip-off < 5mm



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Paint Faded

Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint  
Chip-off < 5mm, Light Scuffing < 50mm



Trunk Condition

Trunk

Door Trim: Scratch



Trunk conditon

Trunk



Roof Condition

Roof		
<b>Pillars Condition</b>		
Left A Pillar		Right A Pillar
Inner Condition: Fair Use Wear		Inner Condition: Light Scuffing
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
<b>Running Board Condition</b>		
Left Running Board		Right Running Board
<b>Windshield Condition</b>		
Front Windshield		
Beading: Mouldings Crack/ Fair Use Wear < 50mm		Rear Windshield
<b>Structural Assessment</b>		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top Beading: Crack/Fair Use Wear<50mm
Head Light Support Condition		
Cowl Top		
Cowl Top		
<b>Rear View Mirror Condition</b>		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror Body: Paint Chip-off < 5mm		Right Hand Side Mirror
Alloy Wheel/ Rim		
Spare Alloy/ Rim Condition		
Wheel Arch		Wheel cover Front Right: Edge/ Scuffs < 80mm

Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	!	Rear Wiper Blade: Crack/ Fair Use Wear	
Panel Condition			
Rear Trunk Panel	✓		

---

## ⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

---

## 擐 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

Controls  Infotainment Display 

Engine Sensors  OBD Connector 

Music System  Camera   
Reverse Camera: External Fitment

### Lights

Headlight  Interior Lights   
Left: Light Scuff Marks < 50mm

Tail Light Cluster  License Plate Light   
Right Tail Lamp: Crack / Fair Use Wear > 5mm

Fog Lights 

Air Conditioning 

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

Parking Sensors  Rear Defogger 

USB Charging Port  Power/ Manual Windows 

## Interiors & Luggage

Dashboard And Instrument Panel   
Dashboard Trim: Light Scuffing/Disfigurement 

Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

### Tyres Depth (Remaining)

LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	No spare tyre		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE