



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 TOYOTA YARIS

E | 134,798 KM

VIN: MHFBT9F31G6061732

Car highlights



Great Parking Assistance

Parking Sensors Rear



Music System

Enjoy your drive with music system



Amazing Comfort
















Power driver seat



Airbag safety










Airbag Driver Front

Basic Details

 Kilometers	134798	 Specs	Yes
 Engine	1.5L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	MHFBT9F31G6061732		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Comfort & Convenience			
Rear Defogger		Central Armrest	



Exteriors

Halogen Headlights



Entertainment

USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Handle: Paint Chip-off < 5mm



Front right door

Panel: Low Visibility Dent < 30mm



Rear left door

Handle: Paint Chip-off < 5mm



Rear right door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm



Right Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Chip<5mm, Light Scuffing<50mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm, Crack/ Misaligned



Hood Condition

Hood



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm



Trunk conditon

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Chip < 8mm	!
Right B to C Pillar Beading	✓	Left C Pillar Chip < 5mm	!
Running Board Condition			
Left Running Board Front Left Sill Trim: Minor Scuffing < 80mm	!	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Light Scuffing < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Front Left: Light Scuffing < 50mm	!
Antenna	✓	Grill Condition	!

Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers





Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Glove Box



Steering Wheel Steering Wheel Fair Use Wear	⚠	Sunvisor	✓
Seat Upholstery Rear Left Seat: Fair Wear/Color Dullness > 80 mm, Leather/ Fabric Fair Use Wear/ Tears	⚠	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet Front Left Floor Carpet: Smudge/Fair Use Wear	⚠	Headliner Front Left: Light Smudge/Disfiguration	⚠
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE