



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 TOYOTA RUSH**

**EX | 120,117 KM**

VIN: MHKEF8BF9LK015793

## Car highlights



### **Great Parking Assistance**

Parking Sensors Rear



### **Music System**

Enjoy your drive with music system



### **Steering Mounted Audio Controls**
















Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**







Power driver seat

## Basic Details

 Kilometers	<b>120117</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MHKEF8BF9LK015793</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>	
Fog Light Front	
 <b>Safety &amp; Security</b>	
Parking Sensors Rear	
 <b>Comfort &amp; Convenience</b>	
Steering Mounted Audio Controls	



## Entertainment

USB Charging Port



Infotainment System



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door  
Handle: Scratch < 50mm



Front right door  
Handle: Light Scuffing < 50mm



Rear left door  
Handle: Scratch < 50mm



Rear right door  
Handle: Scratch < 50mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel  
Condition: Paint Chip-off < 5mm



Right Quarter Panel



### Front Bumper Condition

Front Bumper  
Condition: Misaligned



### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood  
Bonnet: Paint Chip-off < 5mm



### Trunk Condition

Trunk  
Door Trim: Light Scuffing < 50mm



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar Colour Mismatch	!	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Colour Mismatch/ Low Brightness	!
Right B to C Pillar Beading	✓	Left C Pillar	✓
<b>Running Board Condition</b>			
Left Running Board Condition: Colour faded	!	Right Running Board Condition: Colour faded	!
<b>Windshield Condition</b>			
Front Windshield	✓	Rear Windshield	✓
<b>Structural Assessment</b>			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Beading Melted	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
<b>Rear View Mirror Condition</b>			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
<b>Alloy Wheel/ Rim</b>			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
<b>Wheel Arch</b>			
Front Left: Colour faded	!	Antenna	✓
<b>Grill Condition</b>			
Light Scuffing < 50mm	!	Monogram	✓

Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Right AC Vent	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

### Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Gear Shift Knob: Faded, Scratched	⚠
Cup Holder	✓	Glove Box	✓



Steering Wheel	✓	Sunvisor Left: Sunvisor LHSMInor Smudge	⚠
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	⚠	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Rear Left Door: Scratch	⚠	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration	⚠
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<75%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE