



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 BMW X5**

**XDRIVE 35i | 117,608 KM**

VIN: WBAKR0104F0M64931

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats & more





Basic Details

 Kilometers	117608	 Specs	Yes
 Engine	3.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	WBAKR0104F0M64931		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Power Head Rest	
Rear Defogger		Central Armrest	

Automatic Headlights	✓	
 <b>Exteriors</b>		
Fog Light Front	✓	Roof Rails ✓
Running Lights	✓	Rear Bumper Spoiler ✓
HID Headlights	✓	
 <b>Safety &amp; Security</b>		
Navigation	✓	Parking Sensors Front ✓
Parking Sensors Rear	✓	Reverse Camera ✓
Blind Spot Monitor	✓	Traction Control ✓
Airbag Curtain Shield	✓	Airbag Driver Front ✓
ABS	✓	Central Locking ✓
Child Safety Locking	✓	
 <b>Performance</b>		
Paddle Shift	✓	
 <b>Entertainment</b>		
Bluetooth Player	✓	Infotainment System ✓
USB player	✓	





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm		Panel: Paint Chip-off < 5mm, Low Visual Dent < 30mm, Light Scuffing < 50mm	

### Fenders Condition

Left Fender		Right Fender	
		Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Light Scuffing<50mm		Condition: Light Scuffing<50mm	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar

Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board

Rear Right Sill Trim: Light Scuffing < 80mm



## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Condition: Light Scuffing < 80mm



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Wheel cover



Antenna



Grill Condition	✓	Monogram	✓
Window Glass			
Rear Right Window Curtain: minor imperfection	!	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch  
Button(s) Faded





AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓



## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Rear Right Door: Light Scuffing			
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓



## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	No spare tyre		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE