



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 NISSAN MAXIMA

SV | 119,453 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 119453 |  Specs | Yes |
|  Engine | 3.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Leather Trim |  Number of Airbags | 8 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | 1N4AA6APXJC360382 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | | |
|--|--|---|---------------------------------|---|
| <div> Comfort & Convenience</div> | | | | |
| Climate Control AC | |  | Cruise Control |  |
| Rear Armrest with cupholder | |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors | |  | Rear Defogger |  |
| Central Armrest | |  | Remote Engine Start |  |
| Automatic Headlights | |  | | |



Exteriors

Fog Light Front



Running Lights



LED Headlights



Halogen Headlights



Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door |  |
| Rear left door |  | Rear right door Panel: Paint Chip-off < 5mm |  |

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|

Quarter Panels Condition

| | | | |
|--|---|---|---|
| Left Quarter Panel Condition: Dent < 30mm |  | Right Quarter Panel Condition: Dent < 30mm |  |
|--|---|---|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|





Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

| | | | |
|---|---|-------------------------------|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | | Left Rear Alloy/ Rim | |
| Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm | ! | Rim: Alloy Edge/ Scuff < 80mm | ! |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ! |
| | | Light Scuffing < 50mm | |
| Monogram | ✓ | Window Glass | ✓ |

| | | |
|------------------|---|--|
| Wiper | ✓ | |
| Panel Condition | | |
| Rear Trunk Panel | ✓ | |

Engine & Transmission

| | | |
|--------------------------------|---|----------------------|
| Engine | | |
| Engine Body | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Radiator Condition | ✓ | Radiator Coolant ✓ |
| Battery | | |
| Battery Terminal & Tightness | ✓ | |
| Fuel System | | |
| Fuel Cap | ✓ | Fuel Tank ✓ |
| Transmission Operation | | |
| Gear Shifting | ✓ | Drive Axle ✓ |
| Transmission Fluid | ✓ | |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Pedals | ✓ | |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | | |
|------------|---|----------------|
| Keys | | |
| Master Key | ✓ | Spare Key(s) ✓ |

| | | | |
|-------------------------|---|--|---|
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control Cruise Control Switch: Buttons Faded | ⚠ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Navigation System | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Fog Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters | ✓ |



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<75%

RHS Front Tyre

<85%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE