

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 HONDA CIVIC

DX | 150,668 KM

VIN: NLAFC5631HW016089

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

Yes	Specs	GCC	150668	Kilometers	
Basic	Option Type	* ==	1.6L	Engine	•
Front Wheel Drive	Drive	ા∳ા ા∱ા	Automatic	Transmission	
Petrol	Fuel		SEDAN	Body Type	(III)
Exterior Color Grey	Exterior Color	ţ.	Steel Wheels	Wheel Type	
2 Airbags	Number of Airbags	je K	Fabric Trim	Interior Trim	*
2 Keys	Number of keys	Ş	5 Seats	Seating Capacity	Â
			NLAFC5631HW016089	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

🖄 Comfort & Convenience			
Climate Control AC	~	Cruise Control	~
Rear Armrest with cupholder	~	Steering Mounted Audio Controls	~
Rear Defogger	~	Central Armrest	~
Safety & Security			
Parking Sensors Rear	~	Traction Control	~

Airbag Driver Front	~	ABS	
Central Locking	~	Child Safety Locking	~
Exteriors			
Running Lights	 	Halogen Headlights	~
Bluetooth Player	~	USB Charging Port	
USB player	~		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

 \checkmark

🕾 Exterior			
Doors condition			
Front left door	 	Front right door	 Image: A start of the start of
Rear left door Panel: Dent < 30mm, Paint Chip-off < 5mm	(!)	Rear right door Handle: Paint Chip-off < 5mm	(!)
Fenders Condition			
Left Fender	 Image: A start of the start of	Right Fender	 Image: A start of the start of
Quarter Panels Condition			
Left Quarter Panel	 	Right Quarter Panel	 Image: A start of the start of
Front Bumper Condition			
Front Bumper	 Image: A start of the start of		
Rear Bumper Condition			
Rear Bumper	(!)		
Rear Bumper: Light Scuffing < 80mm			
Hood Condition			
Hood	 		
Trunk Condition			
Trunk	~		
Trunk conditon			
Trunk	~		
Roof Condition			
Roof	 Image: A start of the start of		
Pillars Condition			
Left A Pillar	 Image: A start of the start of	Right A Pillar	 Image: A start of the start of
Left A to B Pillar Beading	 Image: A start of the start of	Right A to B Pillar Beading	

Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	~	Left B to C Pillar Beading	~
Right C Pillar Trim	~	Right B to C Pillar	~
Right B to C Pillar Beading	~	Left C Pillar	~
Running Board Condition Left Running Board Condition: Scratch < 80mm Windshield Condition	(!)	Right Running Board	~
Front Windshield	 Image: A start of the start of	Rear Windshield	 Image: A start of the start of
Structural Assessment			
Chassis Condition	 	Radiator Support	\checkmark
Apron	 Image: A start of the start of	Boot Floor	 Image: A start of the start of
Firewall Condition	 	Cowl Top	 Image: A start of the start of
Head Light Support Condition	~		
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror	 	Left Side Mirror	 Image: A start of the start of
Right Side Mirror	~	Right Hand Side Mirror	~
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	~		
Wheel Arch	~	Wheel cover	~
Antenna	~	Grill Condition Light Scuffing < 50mm	(!)
Monogram	~	Window Glass	~
Wiper	~		
Panel Condition			
Rear Trunk Panel	~		

Engine & Transmission

Engine			
Engine Body	 Image: A start of the start of	Engine Performance	~
Engine Oil (Condition & Level)	 	Exhaust System	 Image: A start of the start of
Radiator Condition	 Image: A start of the start of	Radiator Coolant	 Image: A start of the start of
Battery			
Battery Terminal & Tightness	 Image: A start of the start of		
Fuel System			
Fuel Cap	 Image: A start of the start of	Fuel Tank	 Image: A start of the start of
Transmission Operation			
Gear Shifting	 Image: A start of the start of	Drive Axle	 Image: A start of the start of
Transmission Fluid	 Image: A start of the start of		

Steering, Suspension & Brakes			
Steering			
Steering wheel	 Image: A start of the start of		
Brake System			
Parking Brake	 Image: A start of the start of	Brake Master Cylinder	 Image: A start of the start of
Brake Disc & Brake Pad	~	Brake Fluid	 Image: A start of the start of
Pedals	~		
Suspension			
Shock Absorbers	 Image: A start of the start of		

Electricals, Controls & Lights			
Keys			
Master Key	~	Spare Key(s)	
Door Locks			
Child Safety Locking	 		
Dashboard			

Instrument Panel	 		
Airbags			
Airbags	 		
Controls	~	Cruise Control	~
Infotainment Display	 Image: A start of the start of	Engine Sensors	~
OBD Connector	 Image: A start of the start of	Music System	 Image: A start of the start of
Lights			
Headlight Left: Light Scuff Marks < 50mm	(!)	Interior Lights	~
Tail Light Cluster	~	Turn Signal Lights	 Image: A start of the start of
Daylight Running Lights	~	License Plate Light	~
Air Conditioning			
AC Cooling	~	AC Switch	\checkmark
AC System Leaks	 	Center AC Vent	~
Front Right AC Vent	~	Heater	~
Parking Sensors	~	Rear Defogger	 Image: A start of the start of
USB Charging Port	~	Power/ Manual Windows	<

▲ Interiors & Luggage

Dashboard And Instrument Panel	 	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	~	Glove Box	~
Steering Wheel	~	Sunvisor	~
Seat Upholstery	~	Manual Seat Movement	~
Seat Belts	~	Head Rest	
Door Controls And Trim Rear Right Door: Light Scuffing	(!)	Grab Handle	~

Carpet	~	Headliner	 Image: A start of the start of
Rear View Mirror	~	Toolkit	~
Tyres			
Tyres Condition			
Left Hand Side Front Tyre Crack/Uneven Wear	(!)	Left Hand Side Rear Tyre Crack/Uneven Wear	!
Right Hand Side Front Tyre	 Image: A start of the start of	Right Hand Side Rear Tyre	~
Spare Tyre	~		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	No spare		
	tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE