



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2013 NISSAN MAXIMA

SV | 146,393 KM

VIN: 1N4AA5AP8DC843268

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	146393	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Other
 Interior Trim	Fabric Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1N4AA5AP8DC843268		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 Exteriors			
Fog Light Front		Halogen Headlights	



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Handle: Paint Chip-off < 5mm



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm, Original Paint



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm, Paint Chip-off < 5mm, Partially Repainted



Right Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm, Paint Defect



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm, Scuffing>50mm, Chip<5mm, Acid Marks/ Bird Dropping<5mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm, Original Paint



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm, Original Paint, Acid Marks/ Bird Dropping < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar

Inner Condition: Fair Use Wear



Right A Pillar

Inner Condition: Light Scuffing



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar

Left B Pillar

Condition: Light Scuffing Scratch < 50mm



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board

Condition: Light Scuffing < 80mm



Right Running Board

Condition: Light Scuffing < 80mm



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Condition: Driver Side/Scuffing, Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top

Fair Use Wear/Crack<5mm



Rear View Mirror Condition

Left Hand Side Mirror	⚠	Left Side Mirror	✓
Body: Light Scuffing < 50mm			
Right Side Mirror	⚠	Right Hand Side Mirror	✓
Body: Light Scuffing < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face Light Scuffing < 50mm, Alloy	⚠	Rim: Alloy Face Light Scuffing < 50mm, Alloy	⚠
Edge Scuffing > 50mm		Edge Scuffing > 50mm	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Face Light Scuffing < 50mm, Alloy	⚠	Rim: Alloy Edge/Scuffing<80mm, Alloy	⚠
Edge Scuffing < 80mm		Face/Light Scuffing<50mm	
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Dent < 30mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals

Brake Pedal Cover: Crack/Fair Use Wear



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster

Left Tail Lamp: Light Scuffing < 50mm



Turn Signal Lights

Left ORVM: Light Scuffing < 50mm




License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Scuffing/ Disfiguration/ Melted	!	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage	!
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off, Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration	!	Grab Handle	✓
Carpet Front Left Floor Carpet: Smudge/Fair Use Wear	!	Headliner Front Left: Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Spare Tyre	<div></div>		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE