



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MITSUBISHI LANCER EX

GLS HIGH | 100,751 KM

Car highlights



Sunroof

This car has a sunroof



Amazing Comfort
















Power driver seat



Tilt Steering wheel








Tilt steering wheel for extra comfort

Basic Details

 Kilometers	100751	 Specs	Yes
 Engine	1.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JMYSRCY1AGU753012		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience		
Sunroof		
 Safety & Security		
Navigation		Parking Sensors Rear 
Reverse Camera		
 Entertainment		

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Paint Chip-off < 5mm



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm



Fenders Condition

Left Fender

Condition: Dent < 30mm, Scratch < 50mm



Right Fender

Right Fender: Dent < 30mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Front Bumper Condition

Front Bumper

Condition: Fair Use Wear



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	⚠	Left B Pillar	✓
Low Visual Dent < 30mm			
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	⚠
		Front Right Floor Trim: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	⚠	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	⚠
		Beading: Crack/Fair Use Wear<50mm	
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			

Left Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	⚠	Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	⚠
Right Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	⚠	Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	⚠
Spare Alloy/ Rim Condition	✓		
Wheel cover Rear Right: Face/ Scuffs < 50mm	⚠	Antenna	✓
Grill Condition Light Scuffing < 50mm	⚠	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition Rear Trunk Panel Paint Chip Off < 5mm	⚠		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓

Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)

Buttons Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls

Horn: Colour Low Brightness



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System

AUX Input: Not Reading



Sunroof Operation

Sunroof



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights

Left Fog Light: Low Brightness lamps



Air Conditioning

AC Cooling



AC Switch

Button(s) Faded



AC System Leaks



Center AC Vent



Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	
		Rear Left: Switch Minor Color Faded/ Peel-Off	!

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Scuffing/ Disfiguration/ Melted > 80 mm

!

Central Console

Box: Minor Color Low Brightness

!

Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use Wear

!

Steering Wheel

Steering Wheel Fair Use Wear

!

Sunvisor

Left: Sunvisor RHS Minor Disfiguration, Sunvisor RHS Minor Smudge, Sunvisor LHSMInor Smudge

!

Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears

!

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing

!

Grab Handle



Carpet



Headliner

Front Left: Smudge/Disfiguration, Light Smudge/Disfiguration

!

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE