



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 HONDA ACCORD

LXA | 120,943 KM

VIN: LUCCR2621F3401163

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat



Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 120943 |  Specs | Yes |
|  Engine | 2.4L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Brown |
|  Interior Trim | Leather Trim |  Number of Airbags | 8 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | LUCCR2621F3401163 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | | |
|  Safety & Security | | | |
| Parking Sensors Rear |  | Reverse Camera |  |

| | | | |
|--|---|-----------------------|---|
| Traction Control | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Exteriors | | | |
| Running Lights | ✓ | Halogen Headlights | ✓ |
|  Entertainment | | | |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Handle: Paint Chip-off < 5mm, Scratch < 50mm 


Front right door

Panel: Light Scuffing < 50mm, Low Visibility 
Dent < 30mm, Paint Chip-off < 5mm

Rear left door

Handle: Paint Chip-off < 5mm, Scratch < 50mm 

Rear right door


Panel: Light Scuffing < 50mm, Low Visual 
Dent < 30mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender

Condition: Low Visual Dent < 30mm, Paint 
Chip-off < 5mm, Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm 

Right Quarter Panel

Condition: Chip<5mm, Light Scuffing<50mm 

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Low Visibility 
Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber 

Beading Fair Use Wear

Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board

Condition: Scratch < 80mm, Scuff < 80mm



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror

Body: Scratch < 50mm, Paint Chip-off < 5mm



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel cover



Grill Condition

Light Scuffing < 50mm



| | | | |
|----------------------|---|--------------|---|
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | | | |
| Paint Chip Off < 5mm | ! | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|-------------------------|---|---------------------|---|
| Keys | | | |
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |



Interiors & Luggage

| | | | |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
|--------------------------------|---|-----------------|---|

| | | | |
|--|---|----------------------|---|
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | | | |
| Rear Right Door: Light Scuffing/Disfiguration, Light Scuffing | ! | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <85% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <85% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE