



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 NISSAN KICKS

SL | 48,365 KM

VIN: 3N1CP5CP0JL469434

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Great Parking Assistance

360° camera, Front Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat




Basic Details

| | | | |
|--|-------------------|---|--------------------|
|  Kilometers | 48365 |  Specs | Yes |
|  Engine | 1.6L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | 3N1CP5CP0JL469434 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|-----------------------|---|
|  Safety & Security | | | |
| 360 degree Camera |  | Navigation |  |
| Parking Sensors Rear |  | Reverse Camera |  |
| Traction Control |  | Front Camera |  |
| Side Camera |  | Airbag Curtain Shield |  |
| Airbag Driver Front |  | ABS |  |

| | | | |
|--|---|---------------------------------|---|
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Comfort & Convenience | | | |
| Climate Control AC | ✓ | Steering Mounted Audio Controls | ✓ |
| Rear Defogger | ✓ | Central Armrest | ✓ |
| Automatic Headlights | ✓ | | |
|  Exteriors | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Halogen Headlights | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door
Handle: Scratch < 50mm



Front right door
Panel: Light Scuffing < 50mm, Low Visibility
Dent < 30mm, Paint Chip-off < 5mm



Rear left door
Panel: Dent < 30mm, Paint Chip-off < 5mm



Rear right door
Panel: Light Scuffing < 50mm, Low Visual
Dent < 30mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel
Condition: Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk
Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|---|---|--|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar Scratch < 50mm | ! |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board Rear Right Sill Trim: Light Scuffing < 80mm | ! |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ✓ |
| Antenna | ✓ | Grill Condition | ✓ |

| | | | |
|------------------|---|--------------|---|
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | | | |
| Dent < 30mm | ! | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|-----------------------|---|----------------------|---|
| Keys | | | |
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Engine Sensors | ✓ | OBD Connector | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Cigarette Lighter: Cigarette Lighter Missing | ! |
| Cup Holder | ✓ | Glove Box | ✓ |

| | | | |
|--|---|----------------------|---|
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | | | |
| Passenger Seat: Minor Leather/Fabric Fair Use Wear/Tears | ! | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | | | |
| Front Left Door: Light Scuffing | ! | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <90% | LHS Rear Tyre | <90% |
| RHS Front Tyre | <90% | RHS Rear Tyre | <90% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE