



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2015 RENAULT KOLEOS

PE | 103,251 KM

VIN: VF1VYRCY7FC521100

### Car highlights



#### **Four wheel drive**

This car has a Four wheel drive



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**









Power driver seat

Basic Details

 Kilometers	103251	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF1VYRCY7FC521100		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front			
Rear Bumper Spoiler			
Halogen Headlights			
 Comfort & Convenience			
Cruise Control			
Steering Mounted Audio Controls			
Central Armrest			



## Safety & Security

Parking Sensors Rear



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition


#### Front left door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm 

#### Front right door

Handle: Paint Chip-off < 5mm 

#### Rear left door

Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm 

#### Rear right door


Handle: Scratch > 50mm 

### Fenders Condition

#### Left Fender


Condition: Light Scuffing < 50 mm 

#### Right Fender


Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm 

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Low Visual Dent<30mm, Light Scuffing<50mm 


#### Right Quarter Panel

Condition: Dent > 30mm, Light Scuffing<50mm 

### Front Bumper Condition


Front Bumper 

### Rear Bumper Condition

Rear Bumper   
Rear Bumper: Light Scuffing < 80mm

### Hood Condition

#### Hood

Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm 

### Trunk Condition

Trunk 


### Trunk conditon

Trunk 

### Roof Condition


Roof 

#### Pillars Condition

Left A Pillar  
Inner Condition: Fair Use Wear 

Right A Pillar  
Inner Condition: Light Scuffing 

Left A to B Pillar Beading 

Right A to B Pillar Beading 


Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 


Right B to C Pillar  
Light Scuffing < 80mm 

Right B to C Pillar Beading  
Beading Crack/ Tear < 5mm 

Left C Pillar 

#### Running Board Condition

Left Running Board 

Right Running Board  
Condition: Light Scuffing < 80mm 

#### Windshield Condition

Front Windshield 

Rear Windshield 

#### Structural Assessment


Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top  
Beading: Crack/Fair Use Wear<50mm 

Head Light Support Condition 


Cowl Top

Cowl Top 

#### Rear View Mirror Condition

Left Hand Side Mirror 

Left Side Mirror 

Right Side Mirror  
Body: Scratch < 50mm 

Right Hand Side Mirror 

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim 

Left Rear Alloy/ Rim 

Right Front Alloy/ Rim 

Right Rear Alloy/ Rim 

Spare Alloy/ Rim Condition 

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Low Brightness lamps



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors

Rear Sensors: minor imperfection



Rear Defogger

Not Working



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage



Dashboard And Instrument Panel



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use Wear



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery

Driver Seat: Minor Fair Wear/Fade off



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE