



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2012 HYUNDAI SANTA FE

GL | 160,269 KM

VIN: KMHSG81B6CU772241

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	160269	 Specs	Yes
 Engine	2.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	KMHSG81B6CU772241		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	

Central Armrest



Performance

Differential Locks



Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Handle: Paint Chip-off < 5mm

Front right door



Panel: Low Visibility Dent < 30mm

Rear left door



Handle: Paint Chip-off < 5mm

Rear right door



Weather Strip: Minor Fair Use Rubber Wear

Fenders Condition

Left Fender



Condition: Dent < 30mm, Scratch < 50mm

Right Fender



Right Fender: Dent < 30mm, Scratch < 50mm

Quarter Panels Condition

Left Quarter Panel



Condition: Dent > 30mm, Scratch > 50mm,

Right Quarter Panel



Repaired and Painted

Condition: Dent < 30mm, Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm, Scuff/

Disfiguration < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Roof Moulding Condition: Colour fade

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Light Scuffing < 80mm	
		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
Front Left Floor Trim: Light Scuffing < 80mm			

Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			

Cowl Top

Cowl Top	
----------	--

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm		Rim: Alloy Face/ Scuff < 50mm	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm		Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	
Spare Alloy/ Rim Condition			

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			!
Dent > 30mm			

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls

Horn: Colour Low Brightness



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Steering Mounted Audio Controls: Not



Working Properly

Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



Button(s) Faded

AC System Leaks



Center AC Vent



Front Right AC Vent



Heater

Fair Use Wear

Heater Not Working



Rear Blower Switch



Rear Defogger



USB Charging Port





Interiors & Luggage

Dashboard And Instrument Panel



Dashboard Trim: Light Scuffing/Disfiguration

Central Console



Gear Shift Knob: Knob Fair Use Wear

Cup Holder



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage

Seat Upholstery



Passenger Seat: Minor Smudge/Cracks

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Front Left Door: Light Scuffing

Grab Handle



Carpet



Rear Left Floor Mat: Smudge/Burn/Crack Fair Use Wear

Headliner



Front Left: Light Smudge/Disfiguration

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE