



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 DODGE DURANGO

GT | 105,467 KM

VIN: 1C4RDHDG9JC231982

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort









Power driver seat, Memory Seats







Basic Details

 Kilometers	105467	 Specs	Yes
 Engine	3.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	7 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1C4RDHDG9JC231982		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div></div> <div>Comfort & Convenience</div>					
Sunroof		<div></div>	Cruise Control		<div></div>
Memory Seats		<div></div>	Steering Mounted Audio Controls		<div></div>
<div></div> <div>Exteriors</div>					
Fog Light Front		<div></div>			
<div></div> <div>Safety & Security</div>					

Navigation 	Parking Sensors Rear 
Reverse Camera 	
 Entertainment	
USB Charging Port 	Infotainment System 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 


Exterior

Doors condition

Front left door 

Front right door
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door
Panel: Scratch < 50mm, Paint Chip-off < 5mm 


Rear right door
Handle: Scratch < 50mm, Scratch > 50mm, Paint Chip-off < 5mm, Faded 

Fenders Condition

Left Fender
Condition: Scratch < 50mm, Paint Chip-off < 5mm 

Right Fender
Right Fender: Scratch < 50mm, Paint Chip-off < 5mm 

Quarter Panels Condition

Left Quarter Panel
Condition: Paint Chip-off < 5mm, Scratch < 50mm 

Right Quarter Panel
Condition: Scratch < 50mm, Paint Chip-off < 5mm 

Front Bumper Condition

Front Bumper 


Rear Bumper Condition

Rear Bumper 

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Low Visibility 
Dent < 30mm, Paint Chip-off < 5mm

Trunk Condition

Trunk
Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm 

Trunk conditon

Trunk 

Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Minor scratch

Left B to C Pillar Beading



Right C Pillar Trim



Minor scratch

Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board

Condition: Scratch < 80mm, Scuff < 80mm,
Faded



Right Running Board

Front Right Sill Trim: Light Scuffing < 80mm



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip Mark<5mm



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Face/ Scuff < 50mm		Rim: Alloy Face/ Scuff < 50mm, Alloy Face/ Scuff > 50mm, Alloy Edge/ Scuff < 80mm, Alloy Edge/ Scuff > 80mm, Paint Faded/Light Rusting	
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering	
Steering wheel	✓

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Pedals	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) ✓
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Engine Sensors ✓
OBD Connector	✓	Navigation System ✓
Music System	✓	
Sunroof Operation		
Sunroof	✓	
Camera	✓	
Lights		
Headlight	✓	Interior Lights ✓
Tail Light Cluster	✓	Turn Signal Lights ✓
Daylight Running Lights	✓	License Plate Light ✓


Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery Third Row Seat: Seat Upholstery Fair Use Wear	!
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim Rear Right Door: Minor scratch	!
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Spare Tyre	<div></div>		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE