



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 FORD ECOSPORT

TITANIUM | 87,156 KM

VIN: MAJHK3BA0GAR54617

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat














Basic Details

 Kilometers	87156	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MAJHK3BA0GAR54617		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Automatic Headlights	
 Exteriors			
Fog Light Front		Roof Rails	

Rear Bumper Spoiler		Halogen Headlights	
 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Curtain Shield		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Entertainment			
Bluetooth Player		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Dent < 30mm, Scratch < 50mm

Panel: Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	!
		Beading: Crack/Fair Use Wear<50mm	
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓

Wiper 

Panel Condition

Rear Trunk Panel 

Engine & Transmission

Engine

Engine Body 

Engine Performance 

Engine Oil (Condition & Level) 

Exhaust System 

Radiator Condition 

Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Cap 

Fuel Tank 

Transmission Operation

Gear Shifting 

Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake 

Brake Master Cylinder 

Brake Disc & Brake Pad 

Brake Fluid 

Pedals 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys








Master Key 

Spare Key(s) 

Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓






Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	
		Cigarette Lighter: Cigarette Lighter Not Working	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓

Seat Belts		Head Rest	
Door Controls And Trim		Carpet	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Tyres Depth (Remaining)

LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE