



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2013 HONDA CR V

EX | 167,572 KM

VIN: 5J6RM4856DL704236

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	167572	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	5J6RM4856DL704236		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
 Exteriors			
Fog Light Front		Halogen Headlights	



Safety & Security

Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 

Exterior

Doors condition

Front left door		Front right door	
Inner Frame: Light Scuffing < 50mm		Moulding: Light Scuffing < 50mm	
Rear left door		Rear right door	
Inner Frame: Light Scuffing < 80mm		Moulding: Scuffing	

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm		Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Light Scuffing<50mm, Chip<5mm		Condition: Light Scuffing<50mm, Chip<5mm	


Front Bumper Condition

Front Bumper 


Rear Bumper Condition

Rear Bumper
Rear Bumper: Dent > 50mm, Scuffing > 80mm, Crack/ Misaligned 

Hood Condition

Hood
Bonnet: Low Visibility Dent < 30mm 

Trunk Condition

Trunk
Door Trim: Scuffing > 50mm 

Trunk conditon

Trunk 

Roof Condition

Roof 

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
Right B to C Pillar Beading	!	Light Scuffing < 80mm	!
Beading Crack/ Tear < 5mm		Left C Pillar	!
Running Board Condition		Chip < 5mm	
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	!
Firewall Condition	✓	Door Skirting: minor imperfection	
Head Light Support Condition	✓	Cowl Top	!
Cowl Top		Beading: Crack/Fair Use Wear<50mm	
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	!	Left Side Mirror	✓
Body: Light Scuffing < 50mm		Right Hand Side Mirror	✓
Right Side Mirror	!		
Body: Light Scuffing < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	✓
Rim: Alloy Edge Scuffing < 80mm			
Spare Alloy/ Rim Condition	✓		

Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch > 50mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap Cap Holder/ Cable Missing	!	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Steering Mounted Audio Controls: Button(s)
Faded



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster

Hazard Lights: minor imperfection



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent

Light Scuffing



Heater



Rear Blower Switch

Crack



Rear Defogger



USB Charging Port





Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light
Scuffing/Crack



Central Console

Box: Minor Color Low Brightness



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<75%

RHS Front Tyre

<85%

RHS Rear Tyre

<75%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE