



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MITSUBISHI LANCER EX

GLS | 127,322 KM

VIN: JMYSRCY1AGU754452

Car highlights



Sunroof

This car has a sunroof



Music System

Enjoy your drive with music system



Steering Mounted Audio Controls
















Enjoy your drive with steering mounted audio controls



Amazing Comfort










Power driver seat

Basic Details

 Kilometers	127322	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JMYSRCY1AGU754452		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Rear Bumper Spoiler	
Halogen Headlights			
 Comfort & Convenience			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	



Safety & Security

Traction Control



ABS



Central Locking



Child Safety Locking



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm, Paint Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm, Low Visual Dent<30mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Dent > 30mm, Paint Damage/ Low



Brightness

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition


Roof 

Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar 

Running Board Condition

Left Running Board 

Right Running Board 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield 

Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror 

Left Side Mirror 

Right Side Mirror 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim 

Left Rear Alloy/ Rim 

Right Front Alloy/ Rim 

Right Rear Alloy/ Rim 

Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights

Left Fog Light: Lamps Not Working



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



















Rear Defogger



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel Color Faded		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE