



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2017 FORD EXPLORER

BASE 4WD | 121,207 KM

VIN: 1FM5K8B83HGB36512

### Car highlights



#### Four wheel drive

This car has a Four wheel drive



#### Cruise control

Cruise control to drive with ease & comfort



#### Bluetooth
















Enjoy your drive with bluetooth



#### Amazing Comfort










Power driver seat

Basic Details

 Kilometers	121207	 Specs	Yes
 Engine	3.5L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1FM5K8B83HGB36512		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Steering Mounted Audio Controls	
Central Armrest			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
ABS		Central Locking	



## Entertainment

Bluetooth Player



USB Charging Port



Infotainment System







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Condition: Scratched		Condition: Scratched	
Rear left door		Rear right door	
Condition: Scratched		Condition: Scratched	

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratched		Condition: Scratched	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratched			

### Front Bumper Condition

Front Bumper	
Condition: Scratched	

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched	








### Hood Condition

Hood	
Bonnet: Scratched	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
		Condition: Scratched	
Left B Pillar		RHS Pillar B Condition	
		Scratched	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

## Running Board Condition

Left Running Board



Right Running Board



## Windshield Condition

Front Windshield

Condition: Air Bubbles



Rear Windshield



## Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Scratched



Left Side Mirror



Right Side Mirror

Body: Scratched



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim

Alloy Wheel: Scratched



Right Front Alloy/ Rim



Right Rear Alloy/ Rim

Alloy Wheel: Scratched



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Condition: Trim Faded	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Music System	✓
Bluetooth Operations	✓	Camera	✓
Lights			
Lights	✓	Headlight	✓
Interior Lights	✓	Tail Light Cluster	✓
Turn Signal Lights	✓	License Plate Light	✓

Back Up Light	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



## Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Faded	!	Central Console Condition: Gear Knob Scratched, Scratched	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery Driver Seat: Faded	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Stained	!
Door Hinge Condition	✓	Carpet Front floor carpet: Carpet Torn/Damaged, Mat Missing/Torn	!
Headliner Headliner condition: Torn/Dirty	!	Rear View Mirror	✓
Toolkit	✓		

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓



Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE