



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 SUZUKI JIMNY**

**GL | 28,827 KM**

VIN: JS3JB7D15K5100578

## **Car highlights**



### **Low Mileage**

This car has been driven less than 15,000 km  
a year



### **Great Parking Assistance**

Reverse Camera



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**









Power driver seat



Basic Details

 Kilometers	28827	 Specs	Yes
 Engine	1.5L	 Option Type	Basic Option
 Transmission	Manual	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Green
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	4 Seats	 Number of keys	2 Keys
 VIN number	JS3JB7D15K5100578		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>				
Fog Light Front		<div></div>	Halogen Headlights	<div></div>
<div> Performance</div>				
Hill Descent Control		<div></div>		
<div> Safety &amp; Security</div>				
Reverse Camera		<div></div>	Traction Control	<div></div>

Airbag Driver Front	✓	ABS	✓
Central Locking	✓		
 <b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls	✓	Rear Defogger	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Panel: Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm		Condition: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm, Low Visual Dent < 30mm	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Trim: Light Scuffing<80mm			

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Right C Pillar Trim	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron			
Left: Visible Fair Wear use	⚠	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			

Rear Trunk Panel		<div><div></div><div>!</div></div>	
Paint Chip Off < 5mm			
<div><div></div><div>Engine &amp; Transmission</div></div>			
Engine			
Engine Body	<div><div></div><div>!</div></div>	Engine Performance	<div><div></div><div>✓</div></div>
Underbody: Minor Oil Leakage			
Engine Oil (Condition & Level)	<div><div></div><div>✓</div></div>	Exhaust System	<div><div></div><div>✓</div></div>
Radiator Condition	<div><div></div><div>✓</div></div>	Radiator Coolant	<div><div></div><div>✓</div></div>
Battery			
Battery Terminal & Tightness	<div><div></div><div>✓</div></div>		
Fuel System			
Fuel Tank	<div><div></div><div>✓</div></div>		
Transmission Operation			
Gear Shifting	<div><div></div><div>✓</div></div>	Drive Axle	<div><div></div><div>✓</div></div>
4*4 Condition (If Applicable)	<div><div></div><div>✓</div></div>	Transmission Fluid	<div><div></div><div>✓</div></div>
<div><div></div><div>Steering, Suspension &amp; Brakes</div></div>			
Steering			
Steering wheel	<div><div></div><div>✓</div></div>		
Brake System			
Parking Brake	<div><div></div><div>✓</div></div>	Brake Master Cylinder	<div><div></div><div>✓</div></div>
Brake Disc & Brake Pad	<div><div></div><div>✓</div></div>	Brake Fluid	<div><div></div><div>✓</div></div>
Pedals	<div><div></div><div>✓</div></div>		
Suspension			
Shock Absorbers	<div><div></div><div>✓</div></div>		
<div><div></div><div>Electricals, Controls &amp; Lights</div></div>			
Keys			
Master Key	<div><div></div><div>✓</div></div>	Spare Key(s)	<div><div></div><div>✓</div></div>
Dashboard			

Instrument Panel	✓		
Airbags			
Airbags	✓		
Cruise Control	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	
		Passenger Seat: Leather/Fabric Fair Use Wear/ Tears	!
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	
		Rear Left Floor Carpet: Floor Mat Missing	!



## Headliner

Rear Left: Smudge/Disfiguration, Fair Use  
Wear



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

No spare

tyre



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE