



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 PORSCHE CAYENNE

S | 103,499 KM

VIN: WP1ZZZ92ZGLA94593

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort








Power driver seat

Basic Details

| | | | |
|--|-------------------|---|---------------------|
|  Kilometers | 103499 |  Specs | Yes |
|  Engine | 3.6L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WP1ZZZ92ZGLA94593 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | | |
|--|--|--|----------------|--|
| <div> Comfort & Convenience</div> | | | | |
| Panoramic Sunroof | | <div></div> | Cruise Control | <div></div> |
| Steering Mounted Audio Controls | | <div></div> | | |
| <div><div></div> Exteriors</div> | | | | |
| Fog Light Front | | <div></div> | | |
| <div><div></div> Safety & Security</div> | | | | |

| | | | |
|--|---|---------------------|---|
| Parking Sensors Front | ✓ | Navigation | ✓ |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Front Camera | ✓ | Side Camera | ✓ |
|  Entertainment | | | |
| USB Charging Port | ✓ | Infotainment System | ✓ |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|------------------------------------|---|---------------------------------|---|
| Front left door |  | Front right door |  |
| | | Panel: Paint Chip-off < 5mm | |
| Rear left door |  | Rear right door |  |
| Panel: Dent < 30mm, Scratch < 50mm | | Moulding: Light Scuffing < 50mm | |

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|


Quarter Panels Condition

| | | | |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|------------------------------------|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm | |

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|









Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Pillars Condition

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
| Right A to B Pillar |  | Left B Pillar |  |
| Left B Pillar Trim |  | Left B to C Pillar Beading |  |

| | | | |
|---------------------------------------|---|-------------------------------|---|
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ! | Left Rear Alloy/ Rim | ! |
| Rim: Alloy Edge/ Scuff < 80mm | | Rim: Alloy Edge/ Scuff < 80mm | |
| Right Front Alloy/ Rim | ! | Right Rear Alloy/ Rim | ! |
| Rim: Alloy Edge/ Scuff < 80mm | | Rim: Alloy Edge/ Scuff < 80mm | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ✓ |
| Grill Condition | | Monogram | ✓ |
| Light Scuffing < 50mm | ! | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



| | | | |
|-------------------------|---|-----------------------|---|
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Radar (If Equipped) | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Fog Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Dashboard And Instrument Panel



Central Console



Gear Shift Knob: Wear and Tear

Cup Holder



Glove Box



Steering Wheel



Sunvisor



Steering Wheel Fair Use Wear

Seat Upholstery



Manual Seat Movement



Driver Seat: Minor Fair Wear/Fade off

Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Front Left Floor Mat: Smudge/Burn/Crack

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<65%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE