



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2013 NISSAN ALTIMA

S | 108,442 KM

VIN: 1N4AL3A93DC223556

## Car highlights



### Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



### Amazing Comfort

Power driver seat



### Airbag safety

Airbag Driver Front



### Central Arm Rest

Central arm rest for extra comfort

## Basic Details

 Kilometers	<b>108442</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Gold</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>1N4AL3A93DC223556</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 <b>Safety &amp; Security</b>			
Traction Control		Airbag Driver Front	
ABS		Central Locking	

Child Safety Locking



## Exteriors

Halogen Headlights



HID Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm, Dent > 30mm

Rear left door



Panel: Scratch < 50mm

Rear right door



Panel: Light Scuffing < 50mm, Low Visual

Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm

Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm

Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Right Quarter Panel



Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar Low Visual Dent < 30mm		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board Condition: Scratch < 80mm		Right Running Board Condition: Light Scuffing < 80mm
Windshield Condition		
Front Windshield		Rear Windshield
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Spare Alloy/ Rim Condition		
Wheel Arch		Wheel cover Rear Right: Edge/ Scuffs < 80mm
Antenna		Grill Condition

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Scratch < 50mm

## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

## Keys

- Master Key 
- Door Locks
- Child Safety Locking 

## Dashboard

- Instrument Panel 
- Airbags

## Airbags

- Airbags 

- Controls 
- Infotainment Display 

- Engine Sensors 
- OBD Connector 

## Music System

## Lights

- Headlight 
- Left: Light Scuff Marks < 50mm 
- Interior Lights 
- Tail Light Cluster 
- Left Tail Lamp: Crack / Fair Use Wear < 5mm 
- Turn Signal Lights 

## License Plate Light

## Air Conditioning

- AC Cooling 
- AC Switch 
- AC System Leaks 
- Center AC Vent 
- Front Right AC Vent 
- Heater 
- Rear Blower Switch 
- Power/ Manual Windows 

## Interiors & Luggage

### Dashboard And Instrument Panel

- Dashboard And Instrument Panel: Light 
- Scuffing/Crack 
- Central Console 
- Cup Holder 
- Glove Box 

Steering Wheel	!	Sunvisor	!
Steering Wheel Fair Use Wear		Left: Sunvisor LHS Minor Disfiguration, Sunvisor RHS Minor Disfiguration	
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Fair Wear/Fade off			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	!	Toolkit	✓
De Silvered Mirror<10%			

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

### Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE