



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2013 TOYOTA COROLLA**

**XLI | 159,829 KM**

VIN: RKLBC42E1D5315661

## Car highlights



### **Music System**

Enjoy your drive with music system



### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**
















Power driver seat



### **Airbag safety**










Airbag Driver Front





## Basic Details

 Kilometers	<b>159829</b>	 Specs	<b>Yes</b>
 Engine	<b>1.8L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>RKLBC42E1D5315661</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 <b>Exteriors</b>			
Rear Bumper Spoiler		Halogen Headlights	
 <b>Safety &amp; Security</b>			

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Dent < 30mm, Paint Chip-off < 5mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



### Fenders Condition

Left Fender

Condition: Scratch < 50mm, Dent < 30mm



Right Fender

Right Fender: Paint Chip-off < 5mm



### Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm



### Trunk Condition

Trunk



Trunk conditon

Trunk



### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar Low Visual Dent < 30mm	⚠	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Scratch < 80mm, Scuff < 80mm	⚠	Right Running Board Condition: Light Scuffing < 80mm, Light Scuffing < 80mm	⚠
Windshield Condition			
Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm	⚠	Rear Windshield Windsheild Beadings < 50mm	⚠
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Door Skirting: Paint Chip-off < 5mm, Colour Mismatch/ Fade/ Fair Use Wear	⚠
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	⚠
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	⚠	Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	⚠

Right Front Alloy/ Rim  
Rim: Alloy Face/ Scuff < 50mm



Right Rear Alloy/ Rim  
Rim: Alloy Face/ Scuff < 50mm



Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Grill Condition  
Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Paint Chip Off < 5mm



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals 

Suspension

Shock Absorbers 

---

 **Electricals, Controls & Lights**

Keys

Master Key 

Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 


Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Lights

Headlight  
Left: Low Brightness lamps 

Interior Lights 

Tail Light Cluster 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 


Front Right AC Vent 

Heater 

Power/ Manual Windows 

---















 **Interiors & Luggage**

Dashboard And Instrument Panel  
Dashboard Upholstery: Scuffing/ 

Central Console 



Disfiguration/ Melted

Cup Holder		Glove Box	
Steering Wheel Color Faded		Sunvisor	
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Left Door: Light Scuffing		Grab Handle	
Carpet Front Left Floor Mat: Smudge/Burn/Crack		Headliner	
Rear View Mirror		Toolkit	

## Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<75%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE