



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2016 MITSUBISHI LANCER EX**

**GLS | 161,384 KM**

VIN: JMYSRCY1AGU749989

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Great Parking Assistance**

Reverse Camera



### **Steering Mounted Audio Controls**
















Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**










Power driver seat

Basic Details

 Kilometers	161384	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JMYSRCY1AGU749989		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Central Armrest	
 <b>Exteriors</b>			
Fog Light Front		Rear Bumper Spoiler	
Halogen Headlights			



Safety & Security

Reverse Camera



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door	!	Front right door	!
Handle: Scratch < 50mm		Handle: Paint Chip-off < 5mm	
Rear left door	!	Rear right door	!
Handle: Scratch < 50mm		Panel: Paint Defect, Low Visual Dent < 30mm, Light Scuffing < 50mm	

### Fenders Condition

Left Fender	!	Right Fender	!
Condition: Dent < 30mm, Scratch < 50mm		Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	

### Quarter Panels Condition

Left Quarter Panel	!	Right Quarter Panel	✓
Condition: Scratch < 50mm, Dent < 30mm			

### Front Bumper Condition

Front Bumper	✓
--------------	---

### Rear Bumper Condition

Rear Bumper	!
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	!
Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Trunk Condition

Trunk	!
Door Trim: Light Scuffing < 50mm	

### Trunk conditon

Trunk	✓
-------	---

### Roof Condition

Roof	✓
------	---

## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Front Left Floor Trim: Light Scuffing < 80mm

Right Running Board



Front Right Sill Trim: Light Scuffing < 80mm

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Door Skirting: Colour Mismatch/ Fade/ Fair Use Wear



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top

Fair Use Wear/Crack<5mm



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror

Body: Scratch < 50mm



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Right Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	!	Monogram	✓
Broken/ Fair Use Wear			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Dent < 30mm			

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System

Steering Mounted Audio Controls: Button(s)



Faded

Sunroof Operation

Sunroof



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights

Left ORVM: Light Scuffing < 50mm



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Power/ Manual Windows







## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light  
Scuffing/Crack



### Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



### Cup Holder



### Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use  
Wear



### Steering Wheel

Steering Wheel Fair Use Wear



### Sunvisor



### Seat Upholstery



### Manual Seat Movement



### Seat Belts



### Head Rest



### Door Controls And Trim



### Grab Handle



### Carpet



### Headliner



### Rear View Mirror



### Toolkit



## Tyres

### Tyres Condition

#### Left Hand Side Front Tyre



#### Left Hand Side Rear Tyre



#### Right Hand Side Front Tyre



#### Right Hand Side Rear Tyre



#### Spare Tyre



### Tyres Depth (Remaining)

#### LHS Front Tyre

<75%

#### LHS Rear Tyre

<75%

#### RHS Front Tyre

<75%

#### RHS Rear Tyre

<75%

#### Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE