



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MAZDA CX 5

GS | 94,183 KM

VIN: JM8KE4W75H0412272

Car highlights



Great Parking Assistance

Parking Sensors Front, Parking Sensors Rear



Music System

Enjoy your drive with music system



Steering Mounted Audio Controls
















Enjoy your drive with steering mounted audio controls



Amazing Comfort







Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 94183 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Leather Trim |  Number of Airbags | 4 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | JM8KE4W75H0412272 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | | |
|--|--|---|----------------------|---|
|  Safety & Security | | | | |
| Parking Sensors Front | |  | Parking Sensors Rear |  |
|  Comfort & Convenience | | | | |
| Steering Mounted Audio Controls | |  | | |
|  Entertainment | | | | |

USB Charging Port



Infotainment System







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|---|---|---|---|
| Front left door |  | Front right door |  |
| Moulding: Colour mismatch/ Low Brightness | | Handle: Light Scuffing < 50mm | |
| Rear left door |  | Rear right door |  |
| Handle: Paint Chip-off < 5mm | | Moulding: Colour mismatch/ Low Brightness | |

Fenders Condition

| | | | |
|---------------------------|---|------------------------------|---|
| Left Fender |  | Right Fender |  |
| Condition: Scratch < 50mm | | Right Fender: Scratch < 50mm | |


Quarter Panels Condition

| | | | |
|--------------------|--|---------------------|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|--|---------------------|--|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|------------------------------------|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm | |

Hood Condition

| | |
|------------------------------|---|
| Hood |  |
| Bonnet: Paint Chip-off < 5mm | |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

| | | | |
|--------------------------------------|---|--|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ⚠ | Right Running Board | ⚠ |
| Front Left Sill Trim: Scratch < 80mm | | Front Right Sill Trim: Light Scuffing < 80mm | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ⚠ | Left Rear Alloy/ Rim | ✓ |
| Rim: Alloy Face/ Scuff < 50mm | | | |
| Right Front Alloy/ Rim | ⚠ | Right Rear Alloy/ Rim | ✓ |
| Rim: Alloy Edge/ Scuff < 80mm | | | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Antenna | ✓ |
| Grill Condition | ⚠ | Monogram | ✓ |
| Light Scuffing < 50mm | | | |
| Window Glass | ✓ | Wiper | ✓ |

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

| | | | |
|----------------------|---|----------------------------------|---|
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Engine Sensors | ✓ | OBD Connector | ✓ |
| Music System | ✓ | Camera | ! |
| | | Reverse Camera: External Fitment | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--------------------------------|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ! |
| | | Cigarette Lighter: Cigarette Lighter Missing | |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | | Sunvisor | ✓ |
| Steering Wheel Fair Use Wear | ! | | |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |

| | | | |
|------------------------|---|-------------|---|
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <85% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <65% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE