



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 INFINITI QX70**

**LUXE | 100,579 KM**

VIN: JNRCS1MW4KM731067

## Car highlights



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**



Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats & more














## Basic Details

 Kilometers	<b>100579</b>	 Specs	<b>Yes</b>
 Engine	<b>3.7L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>JNRCS1MW4KM731067</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>	
360 degree Camera 	Navigation 
Parking Sensors Front 	Parking Sensors Rear 
Reverse Camera 	Traction Control 
Front Camera 	Side Camera 
Airbag Curtain Shield 	Airbag Driver Front 

ABS		Central Locking	
Child Safety Locking			
 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Ventilated Seat		Power Tailgate/ Power Trunk	
Rear Defogger		Central Armrest	
Automatic Headlights			
 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Running Lights		HID Headlights	
 <b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door  
Moulding: Scratch < 50mm



Front right door  
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door  
Moulding: Scratch < 50mm, Paint Chip-off < 5mm



Rear right door  
Moulding: Paint Chip-off < 5mm



### Fenders Condition

Left Fender



Right Fender  
Condition: Light Scuffing < 50mm



### Quarter Panels Condition

Left Quarter Panel  
Condition: Paint Chip-off < 5mm, Scratch < 50mm



Right Quarter Panel  
Condition: Light Scuffing<50mm, Chip<5mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood  
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm



### Trunk Condition

Trunk  
Door Trim: Light Scuffing < 50mm



### Trunk conditon

Trunk



### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Scratch < 80mm	⚠	Right Running Board Condition: Light Scuffing < 80mm, Light Scuffing < 80mm	⚠
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm	⚠
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	⚠

Rim: Alloy Edge/Scuffing<80mm

Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent





Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel Dashboard Trim: Light Scuffing/Disfiguration	!	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery Rear Left Seat: Minor Fair Use Wear/ Color Dullness	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Fair Use Wear, Light Scuffing	!	Grab Handle	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%

Spare Tyre

<55%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE