



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 MITSUBISHI PAJERO

GLS TOP | 112,948 KM

VIN: JMYLRV95WEJ708956

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	112948	 Specs	Yes
 Engine	3.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JMYLRV95WEJ708956		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 Exteriors	

Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
HID Headlights			



Safety & Security

Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	
Airbag Curtain Shield		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			



Performance

Differential Locks		
--------------------	---	--



Entertainment

Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Moulding: Paint Chip-off < 5mm

Moulding: Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Condition: Light Scuffing < 50 mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	
		Right Foot Board: Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
		Boot Floor	
Apron	✓	Door Skirting: Colour Mismatch/ Fade/ Fair Use Wear	!
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	
		Not Working Properly	!
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	✓
Rim: Alloy Edge/ Scuff < 80mm	!		
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	✓
Rim: Alloy Face/ Scuff < 50mm	!		
Spare Alloy/ Rim Condition	✓		

Wheel cover	!	Antenna	✓
Rear Right: Face/ Scuffs < 50mm			
Grill Condition	!	Monogram	!
Light Scuffing < 50mm		Chrome Low Brightness/ Fair Use Wear	
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Cruise Control 

Infotainment Display  Engine Sensors 

OBD Connector  Music System 

Sunroof Operation 

Sunroof 

Lights 

Headlight  Interior Lights 

Left: Light Scuff Marks < 50mm 

Tail Light Cluster  License Plate Light 

Left Tail Lamp: minor imperfection 

Fog Lights 

Air Conditioning 

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

Heater Not Working 

Rear Blower Switch  Rear Left AC Vent 

Parking Sensors  Rear Defogger 

USB Charging Port  Power/ Manual Windows 

Front Left: minor imperfection 

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Glove Box: Minor Scuffing/Crack/Fair Use Wear	
Steering Wheel Fair Use Wear		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks		Head Rest	
Seat Belts		Rear Left Seat: Fair Use Wear	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Front Left Floor Mat: Smudge/Burn/Crack		Rear Left: Smudge/Disfiguration, Light Scuffing	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE