



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 INFINITI Q50

PREMIUM | 79,285 KM

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat, Memory Seats & more

Basic Details

 Kilometers	79285	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JN1CV7AP2JM700599		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Memory Seats	
Steering Mounted Audio Controls		Central Armrest	
Remote Engine Start			
 Exteriors			
Fog Light Front		Running Lights	



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



ABS



Central Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



150 Point Detailed Inspection Report





We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door		Front right door	
Rear left door		Rear right door	
Condition: Scratched			

Fenders Condition

Left Fender		Right Fender	
Condition: Scratched			


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratched		Condition: Scratched, Dented	

Front Bumper Condition

Front Bumper	
Condition: Scratched	

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched, Tow Hook Cover	
Missing/Broken	








Hood Condition

Hood	
Bonnet: Scratched	

Trunk condition

Trunk	
-------	-------------------------------------------------------------------------------------

Pillars Condition

Left A Pillar		Right A Pillar	
Left B Pillar		RHS Pillar B Condition	
Condition: Scratched			
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

Running Board Condition

Left Running Board



Right Running Board
Condition: Scratched



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Conditon



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror
Body: Scratched



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim
Alloy Wheel: Scratched



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body

Damage & Leaks: Engine Cover Logo
Missing



Engine Performance



Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering

Steering wheel Condition: Trim Faded, Minor Vibration	⚠	Shock absorbers	✓
----------------------------------------------------------	---	-----------------	---

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Suspension

Suspension	✓		
------------	---	--	--

Electricals, Controls & Lights

Keys

Master Key	✓		
------------	---	--	--

Remote Key Operations

Keyless/ Remote Start	✓		
-----------------------	---	--	--

Door Locks

Central Locking Operation	✓	Child Safety Locking	✓
---------------------------	---	----------------------	---

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Controls

Controls	✓	Cruise Control	✓
----------	---	----------------	---

Music System

Music System	✓	Bluetooth Operations	✓
--------------	---	----------------------	---

Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight Left: Scratched	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Push Start Button Chrome Faded	!	Condition: Cover Missing	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery Passenger Seat: Stained	!	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓

Door Hinge Condition



Carpet

Rear Floor Carpet: Stained



Headliner

Headliner condition: Sun Visor Stained



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%

Spare Tyre

No spare

tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE