



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MAZDA CX 5

GS | 97,330 KM

VIN: JM7KFAWL2K0209747

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	97330	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM7KFAWL2K0209747		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Power Folding Mirrors		Central Armrest	
 Safety & Security			
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	

Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Entertainment			
Bluetooth Player	✓	USB player	✓
 Exteriors			
LED Headlights	✓		

150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 

Exterior

Doors condition

Front left door
Handle: Paint Chip-off < 5mm 

Front right door
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm 

Rear left door
Panel: Scratch < 50mm, Paint Chip-off < 5mm 

Rear right door
Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 


Fenders Condition

Left Fender
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm 

Right Fender
Condition: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Quarter Panels Condition


Left Quarter Panel
Condition: Scratch < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm 

Right Quarter Panel
Condition: Low Visual Dent < 30mm, Light Scuffing<50mm 

Front Bumper Condition

Front Bumper 


Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm 

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Trunk Condition

Trunk
Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm 

Trunk conditon

Trunk 

Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar
Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar
Scratch < 50mm



Running Board Condition

Left Running Board



Right Running Board



Front Left Sill Trim: Scratch < 80mm

Front Right Sill Trim: Light Scuffing < 80mm

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip
Mark<5mm, Passenger Side/Stone Chip
Mark<8mm



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	✓
Rim: Alloy Edge Scuffing < 80mm			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	⚠
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓

Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights Left ORVM: Light Scuffing < 50mm	!
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	!	USB Charging Port	✓

Extensive Wear Of Strip

Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light
Scuffing/Crack



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use
Wear



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE