



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 TOYOTA FORTUNER

GXR | 108,784 KM

VIN: MHFKU8FS9J0175437

Car highlights



Power packed

Engine size of 4.0 Litres & 6.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat


















Basic Details

 Kilometers	108784	 Specs	Yes
 Engine	4.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	3 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MHFKU8FS9J0175437		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Central Armrest	
Automatic Headlights			
 Exteriors			

Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 Performance			
Paddle Shift			
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Knees	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Entertainment			
Bluetooth Player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Frame Extension Cover: Low Visual Dent < 30mm



Front right door

Panel: Low Visibility Dent < 30mm



Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	✓
Rim: Alloy Face Light Scuffing < 50mm			
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	!
		Rim: Alloy Edge/Scuffing<80mm	
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓

Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
-------------	---	--------------------	---

Engine Oil (Condition & Level)	✓	Exhaust System	✓
--------------------------------	---	----------------	---

Radiator Condition	✓	Radiator Coolant	✓
--------------------	---	------------------	---

Battery

Battery Terminal & Tightness	✓		
------------------------------	---	--	--

Fuel System

Fuel Cap	✓	Fuel Tank	✓
----------	---	-----------	---

Transmission Operation

Gear Shifting	✓	Gear shift	✓
---------------	---	------------	---

Drive Axle	✓	4*4 Condition (If Applicable)	✓
------------	---	-------------------------------	---

Transmission Fluid	✓		
--------------------	---	--	--

Steering, Suspension & Brakes

Steering

Steering wheel	✓		
----------------	---	--	--

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
---------------	---	-----------------------	---

Brake Disc & Brake Pad	✓	Brake Fluid	✓
------------------------	---	-------------	---

Pedals	✓		
--------	---	--	--

Suspension

Shock Absorbers	✓		
-----------------	---	--	--

Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger Not Working	!	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear !

Central Console

Box: Minor Disfiguration !

Cup Holder		Glove Box	
Steering Wheel Steering Wheel Fair Use Wear		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Left Door: Light Scuffing		Grab Handle	
Carpet Front Left Floor Mat: Smudge/Burn/Crack		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE