



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2018 HONDA CIVIC**

**EX | 100,731 KM**

VIN: NLAFC5674JW002616

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat

















## Basic Details

 Kilometers	<b>100731</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Mid Option</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>NLAFC5674JW002616</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Remote Engine Start			
 <b>Exteriors</b>			

Fog Light Front		Running Lights	
Halogen Headlights			
 <b>Performance</b>			
Paddle Shift			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Entertainment</b>			
Bluetooth Player		USB Charging Port	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm, Light Scuffing<50mm



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Trunk Condition

Trunk



### Trunk condition

Trunk
































### Roof Condition

Roof



### Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Front Left Sill Trim: Minor Scuffing < 80mm			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Edge Scuffing > 50mm		Rim: Alloy Edge Scuffing > 50mm	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Edge Scuffing < 80mm		Rim: Alloy Edge/Scuffing<80mm	
Spare Alloy/ Rim Condition			
Wheel Arch		Wheel cover	
Antenna		Grill Condition	

Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Underbody: Minor Cover Fair Use Wear			
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		Transmission Fluid	

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Front Right Speakers: Minor Scuffing



## Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



---

## Interiors & Luggage

Dashboard And Instrument Panel



Central Console





Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre Crack/Uneven Wear		Left Hand Side Rear Tyre Crack/Uneven Wear	
Right Hand Side Front Tyre Crack/Uneven Wear		Right Hand Side Rear Tyre Crack/Uneven Wear	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<85%
RHS Front Tyre	<65%	RHS Rear Tyre	<85%
Spare Tyre	No spare tyre		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE