



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 RENAULT DUSTER

SE | 68,222 KM

VIN: VF1HSRCH1HA542229

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort



















Power driver seat

Basic Details

 Kilometers	68222	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF1HSRCH1HA542229		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front			
Roof Rails			
Running Lights			
Halogen Headlights			
 Comfort & Convenience			
Cruise Control			
Steering Mounted Audio Controls			
Rear Defogger			
Automatic Headlights			



Safety & Security

Navigation



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Inner Handle: Color/Chrome Dullness



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm



Right Fender

Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm, Light Scuffing<50mm



Right Quarter Panel



Front Bumper Condition

Front Bumper

Condition: Fair Use Wear



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber
Beading Fair Use Wear



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Condition: Light Scuffing < 80mm



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control

Cruise Control Switch: Buttons Faded



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster

Rear Windscreen Brake Lamp: Light Scuffing
< 30mm



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent
Colour Faded



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows





Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear



Central Console



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Seat Upholstery



Rear Left Seat: Minor Smudge/ Crack

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner

Rear Left: Fair Use Wear



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE