



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2014 FORD MUSTANG V6 MANUAL STD | 92,335 KM

VIN: 1ZVBP8AMXE5257789

Car highlights



2 door style

Stylish car design having 2 doors



Amazing Comfort


Power driver seat



Tilt Steering wheel


Tilt steering wheel for extra comfort


Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	✓	Left B Pillar	✓
Right B to C Pillar	✓	Left C Pillar	✓
Running Board Condition Left Running Board Front Left Floor Trim: Light Scuffing < 80mm Windshield Condition	(!)	Right Running Board Condition: Light Scuffing < 80mm	(!)
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	•	Radiator Support	
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	(!)
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			



Airbags			
Airbags	✓		
Cruise Control	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	Power/ Manual Windows	•
Rear Defogger Interiors & Luggage	✓	Power/ Manual Windows	•
0		Power/ Manual Windows Central Console Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing	!
🖺 Interiors & Luggage	**	Central Console Box: Minor Color Low Brightness, Minor	·
Interiors & Luggage Dashboard And Instrument Panel	***	Central Console Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing Steering Wheel	
Interiors & Luggage Dashboard And Instrument Panel Glove Box		Central Console Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing Steering Wheel Color Faded	
Interiors & Luggage Dashboard And Instrument Panel Glove Box Sunvisor		Central Console Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing Steering Wheel Color Faded Seat Upholstery	
Interiors & Luggage Dashboard And Instrument Panel Glove Box Sunvisor Manual Seat Movement		Central Console Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing Steering Wheel Color Faded Seat Upholstery Seat Belts Door Controls And Trim	!**

Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Tyres Depth (Remaining) LHS Front Tyre <85% LHS Rear Tyre <65% RHS Front Tyre <85% RHS Rear Tyre <55% Spare Tyre <45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE