



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 BMW X6**

**XDRIVE 50i | 107,331 KM**

VIN: WBAKU6101G0N49681

## **Car highlights**



### **Power packed**

Engine size of 4.4 Litres & 8.0 cylinders



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats & more

Basic Details

 Kilometers	107331	 Specs	Yes
 Engine	4.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WBAKU6101G0N49681		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Heads up Display		Climate Control AC	
Cruise Control		Memory Seats	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Soft Door Close		Power Folding Mirrors	
Ventilated Seat		Power Tailgate/ Power Trunk	

Power Head Rest	✓	Rear Defogger	✓
Central Armrest	✓	Automatic Headlights	✓
 <b>Safety &amp; Security</b>			
Adaptive cruise control	✓	360 degree Camera	✓
Lane Departure Warning System	✓	Navigation	✓
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Collision Warning System	✓	Traction Control	✓
Front Camera	✓	Side Camera	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Exteriors</b>			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	LED Headlights	✓
 <b>Performance</b>			
Paddle Shift	✓	Hill Descent Control	✓
 <b>Entertainment</b>			
Rear Seat Entertainment	✓	Bluetooth Player	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door  
Handle: Paint Chip-off < 5mm



Front right door  
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door  
Panel: Paint Chip-off < 5mm



Rear right door  
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



### Fenders Condition

Left Fender  
Condition: Light Scuffing < 50 mm



Right Fender  
Condition: Scuffing > 50mm, Paint Chip-off < 5mm



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel  
Condition: Chip<5mm, Light Scuffing<50mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood  
Bonnet: Paint Chip-off < 5mm



### Trunk Condition

Trunk



### Trunk conditon

Trunk  
Lock: minor imperfection



### Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading  
Beading Crack/ Tear < 5mm



Right C Pillar Trim



Right B to C Pillar  
Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Front Left Sill Trim: Scratch < 80mm

Right Running Board



Right Foot Board: Light Scuffing < 80mm

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip  
Mark<5mm, Passenger Side/Stone Chip  
Mark<8mm



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top  
Beading: Crack/Fair Use Wear<50mm



Head Light Support Condition



Cowl Top

Cowl Top  
Fair Use Wear/Crack<5mm



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face Light Scuffing < 50mm



Left Rear Alloy/ Rim

Rim: Alloy Edge Scuffing > 50mm, Alloy Face









		Light Scuffing < 50mm	
Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	✓
Rim: Alloy Face Light Scuffing < 50mm			
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	⚠	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	⚠		
Scratch < 50mm			

## 🔧 Engine & Transmission





















Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

## 🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			

Parking Brake Button Faded		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

## **Electricals, Controls & Lights**

Keys			
Master Key		Spare Key(s)	
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			
Airbags			
Airbags			
Controls		Cruise Control	
Heads Up Display		Infotainment Display	
Engine Sensors		OBD Connector	
Radar (If Equipped)		Navigation System	
Music System			
Sunroof Operation			
Sunroof			
Camera			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		Turn Signal Lights	



Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	!
		Rear: Cigarette Lighter Not Working	
Rear Entertainment	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓








## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	
		Box: Minor Crack/Fair Use Wear/ Scuffing, Minor Color Low Brightness	!
Cup Holder	✓	Glove Box	✓
Steering Wheel		Sunvisor	✓
Steering Wheel Fair Use Wear	!		
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks	!		
Seat Belts	✓	Head Rest	✓
Door Controls And Trim		Carpet	✓
Front Right Door: Light Scuffing, Fair Use Wear	!		
Headliner		Rear View Mirror	✓
Front Left: Light Smudge/Disfiguration	!		
Toolkit	✓		



## Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<75%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE