



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





## 2013 DODGE CHARGER

R/T | 118,366 KM

VIN: 2C3CDXCT8DH540914

### Car highlights



#### **Power packed**

Engine size of 5.7 Litres & 8.0 cylinders



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**











Power driver seat



Basic Details

 Kilometers	118366	 Specs	Yes
 Engine	5.7L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	2C3CDXCT8DH540914		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Remote Engine Start		Automatic Headlights	
 <b>Exteriors</b>			

Fog Light Front	✓	Running Lights	✓
Rear Bumper Spoiler	✓	Halogen Headlights	✓
HID Headlights	✓		
 <b>Safety &amp; Security</b>			
Navigation	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Knees	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 <b>Performance</b>			
Paddle Shift	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door  
Handle: Scratch < 50mm



Front right door  
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door  
Handle: Scratch < 50mm



Rear right door  
Handle: Paint Chip-off < 5mm



### Fenders Condition

Left Fender  
Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm



Right Fender  
Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm



### Quarter Panels Condition

Left Quarter Panel  
Condition: Dent < 30mm, Scratch < 50mm, Repaired and Painted



Right Quarter Panel  
Condition: Low Visual Dent < 30mm, Light Scuffing<50mm



### Front Bumper Condition

Front Bumper  
Condition: Fair Use Wear



### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Refurbished to RTA standards



### Hood Condition

Hood  
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



### Trunk Condition

Trunk



### Trunk conditon

Trunk



### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	!
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	!
Running Board Condition			
Left Running Board Front Left Sill Trim: Scratch < 80mm	!	Right Running Board Condition: Light Scuffing < 80mm, Low Visual Dent < 50mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Condition: Passenger Side/Light Scuffing<50mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top Fair Use Wear/Crack<5mm	!		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	⚠	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	⚠
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	⚠	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	⚠
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Grill Condition	⚠
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

## 🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

## 🚗 Steering, Suspension & Brakes

Steering	
Steering wheel	✓
Brake System	

Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			
Shock Absorbers			
Rear Right Shock Absorbers: minor imperfection	!		

## Electricals, Controls & Lights

Keys			
Master Key			
Button Faded	!		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera			
Reverse Camera: Not Working	!		
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓








Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch Restricted Movement	!
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater Heater Not Working	!
Rear Blower Switch	✓		
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: minor imperfection	!
Cup Holder	✓	Glove Box Glove Box: Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel Color Faded	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Right Door: Light Scuffing/Disfiguration	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE