



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 CHEVROLET TAHOE**

**LT Z71 | 113,548 KM**

**VIN: 1GNSK6KC7FR599455**

## **Car highlights**



### **Power packed**

Engine size of 5.3 Litres & 8.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**










Power driver seat, Memory Seats

## Basic Details

 Kilometers	<b>113548</b>	 Specs	<b>Yes</b>
 Engine	<b>5.3L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>8 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>1GNSK6KC7FR599455</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Cool Box			
 <b>Safety &amp; Security</b>			
Parking Sensors Front		Navigation	

Parking Sensors Rear



Reverse Camera



**Entertainment**

USB Charging Port



Infotainment System



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Moulding: Scratch < 50mm



Front right door

Handle: Light Scuffing < 50mm



Rear left door

Panel: Acid Marks/ Bird Dropping < 5mm,

Paint Chip-off < 5mm



Rear right door



### Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Low Visual

Dent < 30mm, Paint Chip-off < 5mm



Right Fender

Condition: Low Visual Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm



### Quarter Panels Condition

Left Quarter Panel

Condition: Paint Chip-off < 5mm



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm,

Paint Chip-off < 5mm



### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



### Trunk condition

Trunk



### Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar Condition: Scratch < 50mm	!
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	!

Running Board Condition

Left Running Board Condition: Scratch < 80mm	!	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
-------------------------------------------------	---	---------------------------------------------------------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	✓
----------------	---

Windshield Condition

Front Windshield	✓	Rear Windshield	✓
------------------	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Condition: Light Scuffing < 80mm	!
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!

Head Light Support Condition	✓
------------------------------	---

Cowl Top

Cowl Top	✓
----------	---

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Spare Alloy/ Rim Condition			
Grill Condition		Monogram	
Light Scuffing < 50mm			
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
4*4 Condition (If Applicable)		Transmission Fluid	

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Brake Master Cylinder		Brake Disc & Brake Pad	
Brake Fluid			
Pedals			
Suspension			
Shock Absorbers			



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



### Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights

Left Fog Light: Scuff Marks > 50mm



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Parking Sensors



Rear Defogger





USB Charging Port	✓	Rear Entertainment	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	✓
Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear	⚠		
Cup Holder	✓	Glove Box	✓
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear	⚠	Left: Sunvisor LHS Minor Crack/Fair Use Wear	⚠
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Leather/ Fabric Damage/ Tear	⚠		
Seat Belts	✓	Head Rest	✓
Door Controls And Trim		Grab Handle	✓
Front Left Door: Light Scuffing/ Disfiguration	⚠		
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<85%		





## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE