



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 MITSUBISHI MONTERO SPORT**

**GLX | 60,053 KM**

VIN: MMEMC21X7GH021341

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat

















## Basic Details

 Kilometers	<b>60053</b>	 Specs	<b>Yes</b>
 Engine	<b>3.0L</b>	 Option Type	<b>Mid Option</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MMEMC21X7GH021341</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest			
 <b>Exteriors</b>			

Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Halogen Headlights			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Entertainment</b>			
Bluetooth Player		USB player	





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm	
Rear left door Panel: Paint Chip-off < 5mm		Rear right door Panel: Light Scuffing < 50mm	

### Fenders Condition

Left Fender Condition: Paint Chip-off < 5mm		Right Fender Condition: Light Scuffing < 50mm	
--	---	--	---

### Quarter Panels Condition

Left Quarter Panel Condition: Chip<5mm		Right Quarter Panel Condition: Light Scuffing<50mm, Chip<5mm	
---	---	---	---


### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper 

### Hood Condition

Hood  
Bonnet: Paint Chip-off < 5mm 

### Trunk Condition

Trunk 

### Trunk conditon

Trunk 

### Roof Condition

Roof 

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Condition: Scuffing < 100mm

Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Low Visual Dent < 50mm

Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board



Left Foot Board: Light Scuffing < 80mm

Front Right Sill Trim: Light Scuffing < 80mm

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip



Rear Windshield



Mark<5mm, Passenger Side/Stone Chip

Mark<8mm

Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Antenna



Grill Condition



Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm			

## Engine & Transmission

### Engine

Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

## Steering, Suspension & Brakes

### Steering

Steering wheel

### Brake System

Parking Brake Brake Master Cylinder

Brake Disc & Brake Pad Brake Fluid

Pedals

### Suspension

Shock Absorbers

## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



## Lights

Headlight

Left: Low Brightness lamps, Scuff Marks > 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console





			Gear Shift Knob: Knob Missing	
Cup Holder	✓		Glove Box	✓
Steering Wheel Color Faded	!		Sunvisor	✓
Seat Upholstery	✓		Manual Seat Movement	✓
Seat Belts	✓		Head Rest	✓
Door Controls And Trim	✓		Grab Handle	✓
Carpet	✓		Headliner Rear Left: Smudge/Disfiguration	!
Rear View Mirror	✓		Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓		Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓		Right Hand Side Rear Tyre	✓
Spare Tyre	✓			
Tyres Depth (Remaining)				
LHS Front Tyre	<75%		LHS Rear Tyre	<85%
RHS Front Tyre	<85%		RHS Rear Tyre	<85%
Spare Tyre	<85%			



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE