



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 TOYOTA RUSH**

**EX | 72,827 KM**

VIN: MHKEF8BF6KK000702

## Car highlights



### **Great Parking Assistance**

Parking Sensors Rear



### **Music System**

Enjoy your drive with music system



### **Steering Mounted Audio Controls**
















Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**







Power driver seat

## Basic Details

 Kilometers	<b>72827</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MHKEF8BF6KK000702</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>	
Fog Light Front	
 <b>Safety &amp; Security</b>	
Parking Sensors Rear	
 <b>Comfort &amp; Convenience</b>	
Steering Mounted Audio Controls	



## Entertainment

USB Charging Port



Infotainment System



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Inner Frame: Scratch < 50mm



Front right door

Frame: Light Scuffing < 50mm



Rear left door

Inner Frame: Scratch < 80mm



Rear right door

Inner Frame: Light Scuffing < 80mm



### Fenders Condition

Left Fender



Right Fender

Right Fender: Scratch < 50mm



### Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Quarter Panel

Condition: Scratch < 50mm



### Front Bumper Condition

Front Bumper

Condition: Scratch



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm,  
Bumper Reflector Fair Use Wear/ Colour  
Faded



### Hood Condition

Hood



### Trunk Condition

Trunk



Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	!
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	!

### Running Board Condition

Left Running Board Condition: Colour faded	!	Right Running Board Condition: Colour faded	!
---	---	--	---

### Windshield Condition

Front Windshield	✓	Rear Windshield	✓
------------------	---	-----------------	---

### Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!

Head Light Support Condition ✓

Cowl Top

Cowl Top ✓

### Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓

### Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel Arch ✓      Antenna ✓

Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

## Engine & Transmission

### Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

### Steering

Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)  
Missing Button



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



## Controls



Infotainment Display



## Engine Sensors



OBD Connector



## Music System



## Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Right AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel















Dashboard Upholstery: Minor Scuffing/  
Disfiguration/ Melted



Central Console






Cup Holder		Glove Box	
Steering Wheel		Sunvisor Left: Sunvisor LHS Minor Smudge, Sunvisor RHS Minor Smudge	
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Left Door: Minor Scratch		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<85%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE