



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 INFINITI Q50

PREMIUM | 104,694 KM

VIN: JN1CV7AP8HM500014

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat, Memory Seats

Basic Details

 Kilometers	104694	 Specs	Yes
 Engine	2.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JN1CV7AP8HM500014		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Comfort & Convenience</div>				
Climate Control AC		<div></div>	Cruise Control	<div></div>
Memory Seats		<div></div>	Rear Armrest with cupholder	<div></div>
<div><div></div><div>Exteriors</div></div>				
Fog Light Front		<div></div>	Running Lights	<div></div>
<div><div></div><div>Safety & Security</div></div>				

Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm, Paint Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Chip<5mm, Light Scuffing<50mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Refurbished to RTA standards



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk

Lock: minor imperfection



Roof Condition

Roof



Pillars Condition

Left A Pillar

Inner Condition: Fair Use Wear



Right A Pillar

Condition: Light Scuffing<50mm, Chip<5mm



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board

Front Left Floor Trim: Light Scuffing < 80mm



Right Running Board

Condition: Light Scuffing < 80mm



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm



Left Rear Alloy/ Rim

Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm



Right Front Alloy/ Rim

Rim: Alloy Edge Scuffing < 80mm



Right Rear Alloy/ Rim

Rim: Alloy Face/Light Scuffing<50mm, Alloy Edge/Scuffing<80mm



Wheel Arch	✓	Grill Condition	⚠
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body		Engine Performance	
Underbody: Minor Cover Fair Use Wear	⚠	Condition: Engine Vibration Due to Normal Characteristic	⚠
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		

Suspension			
Shock Absorbers	✓		
<hr/>			
<div> <div></div> <div>Electricals, Controls & Lights</div> </div>			
Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster		Turn Signal Lights	✓
Right Tail Lamp: Light Scuffing < 50mm	!		
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	
		Heater Not Working	!
Rear Blower Switch	✓		

Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: minor imperfection	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Color Faded	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle Front Left: Light Scuffing	!
Carpet Trunk Floor Carpet: Fair Use Wear > 80mm	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE