



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 MERCEDES BENZ C 200

ELEGANCE | 119,642 KM

VIN: WDDWF4CB1FR085843

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat

Basic Details

 Kilometers	119642	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WDDWF4CB1FR085843		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
 Safety & Security			
Parking Sensors Front		Navigation	
Parking Sensors Rear		Reverse Camera	
 Entertainment			

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Handle: Scratch < 50mm

Handle: Scratch < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Light Scuffing < 50mm, Faded

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Scratch < 50mm

Condition: Light Scuffing<50mm

Front Bumper Condition

Front Bumper



Condition: Misaligned

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Crack/
Misaligned

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
		Light Scuffing < 80mm	
Right B to C Pillar Beading	✓	Left C Pillar	!
		Dent < 30mm	
Running Board Condition			
Left Running Board	!	Right Running Board	!
Condition: Scuff < 80mm		Front Right Sill Trim: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	!	Rear Windshield	✓
Inner Side: Chip>5mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	

Grill Condition Light Scuffing < 50mm	⚠	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition Rear Trunk Panel Scratch < 50mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle Rear Axle: Cover Broken	⚠	Transmission Fluid	✓

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key

Button Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System

Steering Mounted Audio Controls: Button(s)
Faded



Sunroof Operation

Sunroof



Camera



Lights

Headlight

Right: Beading Melted



Interior Lights

Front Map Reading Light: Centre Roof Light
Cover Faded



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Light Scuffing/ Disfiguration/Melted	!	Box: Lock Damage, Minor Disfiguration	!
Cup Holder	✓	Glove Box	✓
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear	!	Left: Sunvisor LHS Minor Smudge	!
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	
		Front Right Seat: Not Functioning Properly	!
Door Controls And Trim	✓	Grab Handle	
		Rear Left: Minor Scratch	!
Carpet	✓	Headliner	
		Front Left: Headliner Loose	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE