



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 MERCEDES BENZ E 300 AMG KIT | 109,570 KM

VIN: WDDHF5FB2GB177032

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| 冷 Safety & Security | | | |
|----------------------|----------|-------------------------------|----------|
| 360 degree Camera | • | Lane Departure Warning System | ✓ |
| Navigation | ✓ | Parking Sensors Front | • |
| Parking Sensors Rear | ✓ | Reverse Camera | • |
| Blind Spot Monitor | ✓ | Collision Warning System | • |
| Traction Control | ✓ | Front Camera | ✓ |


| Side Camera | ✓ | Airbag Driver Front | ✓ |
|---------------------------------|----------|-----------------------------|----------|
| ABS | ✓ | Central Locking | • |
| Child Safety Locking | ✓ | | |
| © Comfort & Convenience | | | |
| Climate Control AC | • | Cruise Control | • |
| Memory Seats | • | Rear Armrest with cupholder | ✓ |
| Steering Mounted Audio Controls | • | Rear Defogger | ✓ |
| Central Armrest | ✓ | Automatic Headlights | ✓ |
| Performance | | | |
| Paddle Shift | ✓ | | |
| Exteriors | | | |
| Running Lights | ✓ | Halogen Headlights | ~ |
| ₵ [₰] Entertainment | | | |
| Bluetooth Player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
|---|----------|---|----------|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board Condition: Light Scuffing < 80mm | (!) |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ~ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top Beading: Crack/Fair Use Wear<50mm | (!) |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror Body: Light Scuffing < 50mm | ! | Left Side Mirror | • |
| Right Side Mirror Body: Light Scuffing < 50mm | ! | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ~ | | |
| Wheel cover | ✓ | Antenna | • |



| Keys | | | |
|----------------------------------|----------|---|----------|
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Radar (If Equipped) | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch Fair Use Wear | (!) | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | • | Power/ Manual Windows Front Left: Master Switch Buttons Faded | (!) |
| | | | |



🖺 Interiors & Luggage

| Dashboard And Instrument Panel | • | Central Console Box: Minor Disfiguration, Minor Crack/Fair Use Wear/ Scuffing | (!) |
|---|----------|---|----------|
| Cup Holder Rear Central: Pad Missing | ! | Glove Box | ✓ |
| Steering Wheel Steering Wheel Fair Use Wear | (!) | Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear | (!) |
| Seat Upholstery Driver Seat: Minor Fair Wear/Fade off | ! | Manual Seat Movement | ✓ |
| Seat Belts | ~ | Head Rest | ✓ |
| Door Controls And Trim | ~ | Grab Handle | ✓ |
| Carpet | ~ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| Tyroo Corrainon | | | |
|----------------------------|----------|---------------------------|----------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ~ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <85% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <75% |
| Spare Tyre | <45% | | |
| | | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE