



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2016 KIA SPORTAGE

LX | 63,872 KM

VIN: U5YPB81A9GL723856

### Car highlights



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**











Power driver seat




Basic Details

 Kilometers	63872	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	U5YPB81A9GL723856		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>				
Fog Light Front			Roof Rails	
Running Lights			Halogen Headlights	
 <b>Comfort &amp; Convenience</b>				
Cruise Control			Rear Armrest with cupholder	
Steering Mounted Audio Controls			Rear Defogger	

Central Armrest	✓	
 <b>Safety &amp; Security</b>		
Parking Sensors Rear	✓	Reverse Camera ✓
Traction Control	✓	Airbag Driver Front ✓
ABS	✓	Central Locking ✓
Child Safety Locking	✓	
 <b>Performance</b>		
Differential Locks	✓	Crawl Function ✓
 <b>Entertainment</b>		
Bluetooth Player	✓	USB player ✓





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Dent < 30mm, Scratch < 50mm		Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm		Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratch < 50mm, Paint Chip-off < 5mm		Condition: Light Scuffing<50mm, Low Visual Dent < 30mm	

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper 

### Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Damage/ Low Brightness, Paint Chip-off < 5mm 

### Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm 

### Trunk conditon

Trunk 

### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	⚠	Left B Pillar	✓
Light Scuffing < 50mm			
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	⚠	Right Running Board	✓
Front Left Floor Trim: Light Scuffing < 80mm			
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	⚠	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	⚠	Right Hand Side Mirror	✓
Body: Scratch < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓	
Suspension		
Shock Absorbers	✓	

## Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) ✓
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Engine Sensors ✓
OBD Connector	✓	Music System ✓
Camera		
Reverse Camera: Lens Damaged/ Blurred	!	
Lights		
Headlight	✓	Interior Lights ✓
Tail Light Cluster	✓	Turn Signal Lights ✓
Daylight Running Lights	✓	License Plate Light ✓
Fog Lights	✓	
Air Conditioning		
AC Cooling	✓	AC Switch ✓
AC System Leaks	✓	Center AC Vent ✓
Front Right AC Vent	✓	Heater ✓
Rear Defogger	✓	USB Charging Port ✓





## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Box: Minor Disfiguration

Cup Holder



Glove Box



Steering Wheel



Sunvisor



Steering Wheel Fair Use Wear

Seat Upholstery



Manual Seat Movement



Rear Left Seat: Minor Smudge/ Crack

Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Front Left Floor Mat: Smudge/Burn/Crack

Rear Left: Smudge/Disfiguration

Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

&lt;90%

LHS Rear Tyre

&lt;90%

RHS Front Tyre

&lt;90%

RHS Rear Tyre

&lt;90%

Spare Tyre

&lt;65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE