



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MERCEDES BENZ E 250

COUPE AMG | 68,919 KM

VIN: WDDKJ3GB2GF333912

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System















Enjoy your drive with music system



Amazing Comfort










Memory Seats

Basic Details

 Kilometers	68919	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	COUPE	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	9 Airbags
 Seating Capacity	4 Seats	 Number of keys	2 Keys
 VIN number	WDDKJ3GB2GF333912		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Memory Seats			
 Safety & Security			
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	

Traction Control



Performance

Paddle Shift



Exteriors

Running Lights



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Condition: Scratch < 50mm

Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Right C Pillar Trim	✓
Running Board Condition			
Left Running Board	✓	Right Running Board Condition: Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	!
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls

Power Seat: Adjuster Control Not Working



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System

Condition: Language Update Needed



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks

Temp In Running < 14°C



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Seat Heaters



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	
		Passenger Seat: Adjuster Control not Working	!
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	!
		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE