



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 RENAULT KOLEOS**

**PE | 141,770 KM**

VIN: VF1HGRNB5KC314238

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat



Basic Details

|  |                   |   |                     |
|--|-------------------|---|---------------------|
|  Kilometers       | 141770            |  Specs             | Yes                 |
|  Engine           | 2.5L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | VF1HGRNB5KC314238 |   |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   |  | Cruise Control                  |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors  |  | Rear Defogger                   |  |
| Central Armrest  |  | Automatic Headlights            |  |
|  <b>Exteriors</b>                 |   |                                 |   |

|  |   |                     |   |
|--|---|---------------------|---|
| Fog Light Front  | ✓ | Roof Rails          | ✓ |
| Running Lights   | ✓ | Rear Bumper Spoiler | ✓ |
| Halogen Headlights   | ✓ |                     |   |
|  <b>Safety &amp; Security</b> |   |                     |   |
| Parking Sensors Rear   | ✓ | Airbag Driver Front | ✓ |
| ABS  | ✓ | Central Locking     | ✓ |
| Child Safety Locking   | ✓ |                     |   |
|  <b>Entertainment</b>         |   |                     |   |
| Bluetooth Player   | ✓ | USB player          | ✓ |





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|   |   |  |   |
|---|---|--|---|
| Front left door                             |  | Front right door                                   |   |
|   |   | Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
| Rear left door                              |   | Rear right door                                    |  |
| Panel: Scratch < 50mm, Paint Chip-off < 5mm |  |  |   |

### Fenders Condition

|   |   |  |   |
|---|---|--|---|
| Left Fender   |   | Right Fender   |   |
| Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm |  | Condition: Paint Chip-off < 5mm, Light Scuffing < 50mm |  |


### Quarter Panels Condition

|   |   |  |   |
|---|---|--|---|
| Left Quarter Panel                              |   | Right Quarter Panel  |   |
| Condition: Paint Chip-off < 5mm, Scratch < 50mm |  | Condition: Light Scuffing<50mm, Chip<5mm, Low Visual Dent < 30mm |  |

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|


### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper   |   |
| Rear Bumper: Bumper Reflector Fair Use Wear/ Colour Faded |  |

### Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

### Trunk Condition

|  |   |
|--|---|
| Trunk  |   |
| Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm |  |

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|  |   |   |   |
|--|---|---|---|
| Roof   | ⚠ |   |   |
| Roof Moulding Condition: Colour fade   |   |   |   |
| Pillars Condition  |   |   |   |
| Left A Pillar  | ✓ | Right A Pillar                                | ✓ |
| Left A to B Pillar Beading   | ✓ | Right A to B Pillar Beading                   | ✓ |
| Right A to B Pillar  | ✓ | Left B Pillar                                 | ✓ |
| Left B Pillar Trim   | ✓ | Left B to C Pillar Beading                    | ✓ |
| Right C Pillar Trim  | ✓ | Right B to C Pillar<br>Chip < 8mm             | ⚠ |
| Right B to C Pillar Beading  | ✓ | Left C Pillar                                 | ✓ |
| Running Board Condition  |   |   |   |
| Left Running Board   | ⚠ | Right Running Board                           | ⚠ |
| Rear Left Sill Trim: Scratch < 80mm  |   | Front Right Floor Trim: Light Scuffing < 80mm |   |
| Windshield Condition   |   |   |   |
| Front Windshield   |   |   |   |
| Condition: Driver Side/Stone Chip<br>Mark<5mm, Passenger Side/Stone Chip<br>Mark<8mm | ⚠ | Rear Windshield                               | ✓ |
| Structural Assessment  |   |   |   |
| Chassis Condition  | ✓ | Radiator Support                              | ✓ |
| Apron  | ✓ | Boot Floor                                    | ✓ |
| Firewall Condition   | ✓ | Cowl Top                                      | ✓ |
| Head Light Support Condition   | ✓ |   |   |
| Cowl Top   |   |   |   |
| Cowl Top   | ✓ |   |   |
| Rear View Mirror Condition   |   |   |   |
| Left Hand Side Mirror  | ✓ | Left Side Mirror                              | ✓ |
| Right Side Mirror  | ✓ | Right Hand Side Mirror                        | ✓ |
| Alloy Wheel/ Rim   |   |   |   |
| Left Front Alloy/ Rim  | ⚠ | Left Rear Alloy/ Rim                          | ⚠ |
| Rim: Alloy Face/ Scuff < 50mm  |   | Rim: Alloy Face/ Scuff < 50mm                 |   |
| Right Front Alloy/ Rim   | ⚠ | Right Rear Alloy/ Rim                         | ⚠ |
| Rim: Alloy Face/ Scuff < 50mm  |   | Rim: Alloy Face/ Scuff < 50mm                 |   |

|                            |   |  |   |
|----------------------------|---|--|---|
| Spare Alloy/ Rim Condition | ✓ |  |   |
| Wheel Arch                 | ✓ | Wheel cover                              | ✓ |
| Antenna                    | ✓ | Grill Condition<br>Light Scuffing < 50mm | ! |
| Monogram                   | ✓ | Window Glass                             | ✓ |
| Wiper                      | ✓ |  |   |
| Panel Condition            |   |  |   |
| Rear Trunk Panel           | ✓ |  |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Cap                       | ✓ | Fuel Tank          | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

## Steering, Suspension & Brakes

|                       |   |                        |   |
|-----------------------|---|------------------------|---|
| Steering              |   |                        |   |
| Steering wheel        | ✓ |                        |   |
| Brake System          |   |                        |   |
| Brake Master Cylinder | ✓ | Brake Disc & Brake Pad | ✓ |
| Brake Fluid           | ✓ |                        |   |
| Pedals                | ✓ |                        |   |

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)

Buttons Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows







## Interiors & Luggage

|  |   |   |   |
|--|---|---|---|
| Dashboard And Instrument Panel   | ✓ | Central Console<br>Box: Minor Crack/Fair Use Wear/ Scuffing | ! |
| Cup Holder   | ✓ | Glove Box<br>Glove Box: Minor Scuffing/Crack/Fair Use Wear  | ! |
| Steering Wheel<br>Steering Wheel Fair Use Wear   | ! | Sunvisor  | ✓ |
| Seat Upholstery<br>Driver Seat: Minor Cigarette Burn                                     | ! | Manual Seat Movement  | ✓ |
| Seat Belts   | ✓ | Head Rest   | ✓ |
| Door Controls And Trim<br>Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing | ! | Grab Handle   | ✓ |
| Carpet<br>Trunk Floor Carpet: Stain < 80mm   | ! | Headliner   | ✓ |
| Rear View Mirror   | ✓ | Toolkit   | ✓ |



## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Tyres Depth (Remaining)    |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <85% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <85% |
| Spare Tyre                 | <75% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE