



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2013 HONDA ACCORD

LX A | 189,931 KM

VIN: 1HGCR2626DA602782

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Running Lights

This car has a Running lights



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat








Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 189931 |  Specs | Yes |
|  Engine | 2.4L |  Option Type | Basic Option |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 3 Keys |
|  VIN number | 1HGCR2626DA602782 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Central Armrest |  |
|  Exteriors | | | |
| Running Lights |  | Halogen Headlights |  |
|  Safety & Security | | | |

| | | | |
|--|---|---------------------|---|
| Traction Control |  | Airbag Driver Front |  |
| ABS |  | Central Locking |  |
| Child Safety Locking |  | | |
|  Entertainment | | | |
| USB player |  | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Handle: Paint Chip-off < 5mm



Front right door

Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Beading: Rubber Crack/ Tear < 5mm



Rear right door

Handle: Scratch < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm



Front Bumper Condition

Front Bumper

Moulding: Fair Use Wear



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Low Visibility Dent < 30mm, Light Scuffing < 50mm



Trunk Condition

Trunk




Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber Beading Fair Use Wear 

Pillars Condition

Left A Pillar  Right A Pillar 

Left A to B Pillar Beading  Right A to B Pillar Beading 

Right A to B Pillar  Left B Pillar 

Left B Pillar Trim  Left B to C Pillar Beading 

Right C Pillar Trim  Right B to C Pillar 

Right B to C Pillar Beading  Left C Pillar 

Running Board Condition

Left Running Board Condition: Light Scuffing < 80mm  Right Running Board Condition: Light Scuffing < 80mm 

Windshield Condition

Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm  Rear Windshield 

Structural Assessment

Chassis Condition  Radiator Support 

Apron  Boot Floor 

Firewall Condition  Cowl Top Beading: Crack/Fair Use Wear<50mm 

Head Light Support Condition 

Cowl Top

Cowl Top Fair Use Wear/Crack>5mm 

Rear View Mirror Condition

Left Hand Side Mirror Body: Paint Faded  Left Side Mirror 

Right Side Mirror Body: Light Scuffing < 50mm, Paint Defects  Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim  Left Rear Alloy/ Rim 

Rim: Alloy Edge Scuffing > 50mm

Rim: Alloy Edge Scuffing > 50mm

Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Rim: Alloy Edge/Scuffing>80mm

Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Antenna



Grill Condition



Monogram



Window Glass



Wiper



Operation: minor imperfection

Panel Condition

Rear Trunk Panel



Scratch < 50mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle

Rear Axle: minor imperfection



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

| | | | |
|------------------------|---|-----------------------|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |



Electricals, Controls & Lights

Keys

| | | | |
|---------------|---|--------------|---|
| Master Key | ! | Spare Key(s) | ✓ |
| Fair Use Wear | | | |

Door Locks

| | | | |
|----------------------|---|--|--|
| Child Safety Locking | ✓ | | |
|----------------------|---|--|--|

Dashboard

| | | | |
|------------------|---|--|--|
| Instrument Panel | ✓ | | |
|------------------|---|--|--|

Airbags

| | | | |
|---------|---|--|--|
| Airbags | ✓ | | |
|---------|---|--|--|

| | | | |
|----------|---|----------------|---|
| Controls | ✓ | Cruise Control | ✓ |
|----------|---|----------------|---|

Infotainment Display

| | | | |
|--|---|----------------|---|
| Infotainment Display: Display Low Brightness | ! | Engine Sensors | ✓ |
|--|---|----------------|---|

| | | | |
|---------------|---|--|--|
| OBD Connector | ✓ | | |
|---------------|---|--|--|

Music System

| | | | |
|---|---|--|--|
| Steering Mounted Audio Controls: Button(s) Faded | ! | | |
|---|---|--|--|

Lights

| | | | |
|--------------------------------|---|-----------------|---|
| Headlight | ! | Interior Lights | ✓ |
| Left: Light Scuff Marks < 50mm | | | |

Tail Light Cluster

| | | | |
|--|---|--------------------|---|
| Right Tail Lamp: Crack / Fair Use Wear < 5mm | ! | Turn Signal Lights | ✓ |
|--|---|--------------------|---|

| | | | |
|-------------------------|---|--|--|
| Daylight Running Lights | ✓ | | |
|-------------------------|---|--|--|

| | | | |
|---------------------|---|--|--|
| License Plate Light | ✓ | | |
|---------------------|---|--|--|

Air Conditioning

| | | | |
|------------|---|-----------|---|
| AC Cooling | ✓ | AC Switch | ✓ |
|------------|---|-----------|---|

| | | | |
|-----------------|---|----------------|---|
| AC System Leaks | ✓ | Center AC Vent | ✓ |
|-----------------|---|----------------|---|

| | | | |
|------------------------------|---|-------------------|---|
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger Not Working | ! | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Box: Minor Crack/Fair Use Wear/ Scuffing | ! |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor Left: Sunvisor RHS Vanity Mirror Light Not Working, Sunvisor LHSMInor Smudge, Sunvisor RHS Minor Smudge | ! | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Grab Handle | ✓ | Carpet Front Left Floor Carpet: Smudge/Fair Use Wear | ! |
| Headliner Rear Left: Fair Use Wear/Crack | ! | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |

Spare Tyre

No spare
tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE