



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 TOYOTA RUSH

EX | 56,202 KM

VIN: MHKEF8BF7KK005715

Car highlights



Great Parking Assistance

Parking Sensors Rear



Music System

Enjoy your drive with music system



Steering Mounted Audio Controls
















Enjoy your drive with steering mounted audio controls



Amazing Comfort







Power driver seat

Basic Details

 Kilometers	56202	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MHKEF8BF7KK005715		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Fog Light Front	
 Safety & Security	
Parking Sensors Rear	
 Comfort & Convenience	
Steering Mounted Audio Controls	



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Frame: Light Scuffing < 50mm



Rear left door

Frame: Light Scuffing < 50mm



Rear right door

Frame: Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Chip<5mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm, Colour Mismatch/ Low Brightness



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber 


Beading Fair Use Wear

Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 


Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar 


Running Board Condition

Left Running Board
Condition: Light Scuffing < 80mm 

Right Running Board
Condition: Faded 

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip
Mark<5mm, Passenger Side/Stone Chip
Mark<8mm 


Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor
Condition: Light Scuffing < 80mm 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top


Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror
Body: Chip < 5mm, Light Scuffing < 50mm 

Left Side Mirror 

Right Side Mirror
Body: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim 

Left Rear Alloy/ Rim 

Rim: Alloy Edge Scuffing > 50mm

Right Front Alloy/ Rim

Rim: Alloy Edge Scuffing < 80mm



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel Arch

Rear Left: Scratch



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass

Front Right: Light Scuffing < 50mm



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
------------	---	--------------	---

Door Locks

Child Safety Locking	✓		
----------------------	---	--	--

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Airbags

Airbags	✓		
---------	---	--	--

Controls	✓	Infotainment Display	✓
----------	---	----------------------	---

Engine Sensors	✓	OBD Connector	✓
----------------	---	---------------	---

Music System	✓		
--------------	---	--	--

Lights

Headlight Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
---	---	-----------------	---

Tail Light Cluster	✓	Turn Signal Lights	✓
--------------------	---	--------------------	---

License Plate Light	✓	Fog Lights	✓
---------------------	---	------------	---

Air Conditioning

AC Cooling	✓	AC Switch	✓
------------	---	-----------	---

AC System Leaks	✓	Center AC Vent	✓
-----------------	---	----------------	---

Front Right AC Vent	✓	Heater	✓
---------------------	---	--------	---

Rear Blower Switch	✓	Rear Left AC Vent	✓
--------------------	---	-------------------	---

Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Arm Rest: Minor Crack/ Tear Fabric	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Rear Right Seat: Leather/ Fabric Fair Use Wear	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner Rear Left: Smudge/Disfiguration, Light Scuffing	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE